



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Ciel Senior Living of the Tri-Cities	Provider Number	2449
Address	7255 W GRANDRIDGE BLVD ,	Approval Status	Disapproved
City, State, Zip	Kennewick, WA 99336	Facility Type	Residential Care

On 8/25/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

1 Abatement of Electrical Hazards

Abatement of unsafe conditions and electrical hazards. Conditions that constitute an electrical shock or fire hazard shall be abated..

(IFC 603.2 2021)

Corrected

2 Open electrical terminations

Open junction boxes and open-wiring splices shall be prohibited. Approved covers shall be provided for all switch and electrical outlet boxes.

(IFC 603.2.2, 2021)

Corrected

3 Relocatable power taps and current taps

Relocatable power taps and current taps. The construction and use of current taps and relocatable power taps shall be in accordance with NFPA 70 and this code.

(IFC 603.5, 2021)

Corrected

4 Application and Use

603.5.2 Application and use. Relocatable power taps and current taps shall be directly connected to a permanently installed receptacle.
Exceptions:
1. Where approved for use in a Group A occupancy or in a meeting room in a Group B occupancy, not more than five relocatable power taps shall be permitted to be connected together or connected to an extension cord for temporary use to supply power to electronic equipment.
2. Current taps and relocatable power taps shall not be required to connect directly to a permanently installed receptacle outlet where used for 90 days or less for the purpose of testing the performance of such devices.

(IFC 603.5.2, 2021)

Corrected



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Ciel Senior Living of the Tri-Cities	Provider Number	2449
Address	7255 W GRANDRIDGE BLVD ,	Approval Status	Disapproved
City, State, Zip	Kennewick, WA 99336	Facility Type	Residential Care

On 8/25/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

5 Extension Cords

Extension cords. Extension cords shall not be a substitute for permanent wiring and shall be listed and labeled in accordance with UL 817. Extension cords shall not be affixed to structures, extended through walls, ceilings or floors, or under doors or floor coverings, nor shall such cords be subject to environmental damage or physical impact. Extension cords shall be used only with portable appliances. Extension cords marked for indoor use shall not be used outdoors. (IFC 603.6 2021)	Corrected
--	-----------

6 Portable, Electric Space Heaters

Where not prohibited by other sections of this code, portable, electric space heaters shall be permitted to be used in all occupancies in accordance with Sections 603.9.1 through 603.9.5. (IFC 603.9 2021)	Corrected
---	-----------

7 Emergency Operation - Elevator Operation, Maint & Fire Service

Existing elevators with a travel distance of 25 feet (7620 mm) or more shall comply with the requirements in Chapter 11. New elevators shall be provided with Phase I emergency recall operation and Phase II emergency in-car operation in accordance with ASME A17.1/CSA B44. (IFC 604.2, 2021)	Corrected
--	-----------

8 Owner's Responsibility

	Corrected
--	-----------



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name Ciel Senior Living of the Tri-Cities
Address 7255 W GRANDRIDGE BLVD ,
City, State, Zip Kennewick, WA 99336

Provider Number 2449
Approval Status Disapproved
Facility Type Residential Care

On 8/25/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

9 Penetrations - Maintaining Protection

Materials and firestop systems used to protect membrane and through penetrations in fire-resistance-rated construction and construction installed to resist the passage of smoke shall be maintained. The materials and firestop systems shall be securely attached to or bonded to the construction being penetrated with no openings visible through or into the cavity of the construction. Where the system design number is known, the system shall be inspected to the listing criteria and manufacturer's installation instructions.

(IFC 703.1 2021)

Corrected

10 Inspection and Maintenance

Opening protectives in fire-resistance-rated assemblies shall be inspected and maintained in accordance with NFPA 80. Opening protectives in smoke barriers shall be inspected and maintained in accordance with NFPA 80 and NFPA 105. Openings in smoke partitions shall be inspected and maintained in accordance with NFPA 105. Fire doors and smoke and draft control doors shall not be blocked, obstructed, or otherwise made inoperable. Fusible links shall be replaced promptly whenever fused or damaged. Opening protectives and smoke and draft control doors shall not be modified.

(IFC 705.2 2021)

Corrected

11 Hold-Open Devices and Closers

Hold-open devices and automatic door closers, where provided, shall be maintained. During the period that such device is out of service for repairs, the door it operates shall remain in the closed position.

(IFC 705.2.3 2021)

Corrected

12 Door Operation

Swinging fire doors shall close from the full-open position and latch automatically.

(IFC 705.2.4 2021)

Corrected



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Ciel Senior Living of the Tri-Cities	Provider Number	2449
Address	7255 W GRANDRIDGE BLVD ,	Approval Status	Disapproved
City, State, Zip	Kennewick, WA 99336	Facility Type	Residential Care

On 8/25/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

13 Duct and Air Transfer Openings - Maintaining Protection

Dampers protecting ducts and air transfer openings shall be inspected and maintained in accordance with NFPA 80 and NFPA 105. Other products or materials used to protect the openings for ducts and air transfer openings shall be securely attached to or bonded to the construction containing the duct or air transfer opening, without visible openings through or into the cavity of the construction. Any damaged products or materials protecting duct and air transfer openings shall be repaired, restored or replaced. (IFC 706.1 2018)	Facility was unable to provide documentation that the 4 year fire/smoke damper inspection had been performed. Facility states it is scheduled for Sept.
---	--

14 Testing and Maintenance

Sprinkler systems shall be tested and maintained in accordance with Section 901. (IFC 903.5 2021)	Corrected
--	-----------

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Ciel Senior Living of the Tri-Cities	Provider Number	2449
Address	7255 W GRANDRIDGE BLVD ,	Approval Status	Disapproved
City, State, Zip	Kennewick, WA 99336	Facility Type	Residential Care

On 8/25/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

15 Portable Fire Extinguishers - General Requirements

Portable fire extinguishers shall be selected, installed and maintained in accordance with this section and NFPA 10. Exceptions: 1. The distance of travel to reach an extinguisher shall not apply. The travel distance to reach an extinguisher shall not apply to the spectator seating portions of Group A-5 occupancies. 2. Thirty-day inspections shall not be required and maintenance shall be allowed to be once every three years for dry-chemical or halogenated agent portable fire extinguishers that are supervised by a listed and approved electronic monitoring device, provided that all of the following conditions are met: 2.1. Electronic monitoring shall confirm that extinguishers are properly positioned, properly charged and unobstructed. 2.2. Loss of power or circuit continuity to the electronic monitoring device shall initiate a trouble signal. 2.3. The extinguishers shall be installed inside of a building or cabinet in a noncorrosive environment. 2.4. Electronic monitoring devices and supervisory circuits shall be tested every 3 years when extinguisher maintenance is performed. 2.5. A written log of required hydrostatic test dates for extinguishers shall be maintained by the owner to verify that hydrostatic tests are conducted at the frequency required by NFPA 10. 3. In Group I-3, portable fire extinguishers shall be permitted to be located at staff locations. (IFC 906.2 2021)	Corrected
---	-----------

16 Unobstructed and Unobscured

Manual fire alarm boxes shall be provided with ready access, unobstructed, unobscured and visible at all times. (IFC 907.4.2.6 2021)	Corrected
--	-----------

Initials of Authorized Facility Representative: _____



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name Ciel Senior Living of the Tri-Cities
Address 7255 W GRANDRIDGE BLVD ,
City, State, Zip Kennewick, WA 99336

Provider Number 2449
Approval Status Disapproved
Facility Type Residential Care

On 8/25/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

17 Inspection, Testing and Maintenance

The maintenance and testing schedules and procedures for fire alarm and fire detection systems shall be in accordance with Sections 907.8.1 through 907.8.5 and NFPA 72. Records of inspection, testing and maintenance shall be maintained. (IFC 907.8 2021)	Corrected
--	-----------

18 Smoke Detector Sensitivity

Smoke detector sensitivity shall be checked within one year after installation and every alternate year thereafter. After the second calibration test, where sensitivity tests indicate that the detector has remained within its listed and marked sensitivity range (or 4-percent obscuration light grey smoke, if not marked), the length of time between calibration tests shall be permitted to be extended to a maximum of 5 years. Where the frequency is extended, records of detector-caused nuisance alarms and subsequent trends of these alarms shall be maintained. In zones or areas where nuisance alarms show any increase over the previous year, calibration tests shall be performed. (IFC 907.8.3 2021)	Corrected
--	-----------

19 Inspection and Maintenance

Fire department connections shall be periodically inspected, tested and maintained in accordance with NFPA 25. Records of inspection, testing and maintenance shall be maintained. (IFC 912.7 2021)	The following violation was observed: A deficiency was noted on the July 2024 hydrostatic test report, has not been corrected. All inspection reports must verify that the system has no deficiencies, or document that all deficiencies have been corrected.
--	---

20 Maintenance

Carbon monoxide alarms and carbon monoxide detection systems shall be maintained in accordance with NFPA 72. Carbon monoxide alarms and carbon monoxide detectors that become inoperable or begin producing end-of-life signals shall be replaced. (IFC 915.6 2021 WAC)	Corrected
--	-----------



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name Ciel Senior Living of the Tri-Cities
Address 7255 W GRANDRIDGE BLVD ,
City, State, Zip Kennewick, WA 99336

Provider Number 2449
Approval Status Disapproved
Facility Type Residential Care

On 8/25/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

21 Illumination Level Under Emergency Power

initial illumination that is not less than an average of 1 footcandle (11 lux) and a minimum at any point of 0.1 footcandle (1 lux) measured along the path of egress at floor level. Illumination levels shall be permitted to decline to 0.6 footcandle (6 lux) average and a minimum at any point of 0.06 footcandle (0.6 lux) at the end of the emergency lighting time duration. A maximum-to-minimum illumination uniformity ratio of 40 to 1 shall not be exceeded. In Group I-2 occupancies, failure of a single lamp in a luminaire shall not reduce the illumination level to less than 0.2 foot-candle (2.2 lux).

(IFC 1008.3.5 2021)

Corrected

22 Maintenance

Emergency and standby power systems shall be maintained in accordance with NFPA 110 and NFPA 111 such that the system is capable of supplying service within the time specified for the type and duration required.

(IFC 1203.4 2021)

Corrected



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Ciel Senior Living of the Tri-Cities	Provider Number	2449
Address	7255 W GRANDRIDGE BLVD ,	Approval Status	Disapproved
City, State, Zip	Kennewick, WA 99336	Facility Type	Residential Care

On 8/25/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

23 Securing Compressed Gas Containers, Cylinders and Tanks

Compressed gas containers, cylinders and tanks shall be secured to prevent falling caused by contact, vibration or seismic activity. Securing of compressed gas containers, cylinders and tanks shall be by one of the following methods: 1. Securing containers, cylinders and tanks to a fixed object with one or more restraints. 2. Securing containers, cylinders and tanks on a cart or other mobile device designed for the movement of compressed gas containers, cylinders or tanks. 3. Nesting of compressed gas containers, cylinders and tanks at container filling or servicing facilities or in sellers' warehouses not open to the public. Nesting shall be allowed provided that the nested containers, cylinders or tanks, if dislodged, do not obstruct the required means of egress. 4. Securing of compressed gas containers, cylinders and tanks to or within a rack, framework, cabinet or similar assembly designed for such use. Exception: Compressed gas containers, cylinders and tanks in the process of examination, filling, transport or servicing. (IFC 5303.5.3 2021)	Corrected
---	------------------

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name Ciel Senior Living of the Tri-Cities
Address 7255 W GRANDRIDGE BLVD,
City, State, Zip Kennewick, WA 99336

Provider Number 2449
Approval Status Disapproved
Facility Type Residential Care

On 8/25/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

24 Fire Drills

In all Group I, Group E, and Group R2 Occupancies licensed by the state, at least twelve planned and unannounced fire drills shall be held every year. Drills shall be conducted quarterly on each shift in Group I and Group R2, Occupancies and monthly in Group E Occupancies to familiarize personnel with signals and emergency action required under varied conditions. A detailed written record of all fire drills shall be maintained and available for inspection at all times. When drills are conducted between 9:00 p.m. and 6:00 a.m., a coded announcement may be used instead of audible alarms. Fire drills shall include the transmission of a fire alarm signal and simulation of emergency conditions. The fire alarm monitoring company shall be notified prior to the activation of the fire alarm system for drill purposes and again at the conclusion of the transmission and restoration of the fire alarm system to normal mode.


(WAC 212-12-044)


Corrected

Next inspection scheduled on or after: 9/24/2025

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Authorized Representative


Signature

 RANDY TODD
Print Name and Title

Deputy State Fire Marshal Alan Harlan
2803 156TH AVE SE
Bellevue WA 98007
(425) 495-7121


Signature



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name Ciel Senior Living of the Tri-Cities
Address 7255 W GRANDRIDGE BLVD ,
City, State, Zip Kennewick, WA 99336

Provider Number 2449
Approval Status Disapproved
Facility Type Residential Care

On 4/21/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

1 Abatement of Electrical Hazards

Abatement of unsafe conditions and electrical hazards. Conditions that constitute an electrical shock or fire hazard shall be abated..

(IFC 603.2 2021)

The following violations were observed:

Following were open junction boxes:

NW2-L3
NW1-L3
NW1-L2
NW1-L1
NE1-L1
NE1-L2

2 Open electrical terminations

Open junction boxes and open-wiring splices shall be prohibited. Approved covers shall be provided for all switch and electrical outlet boxes.

(IFC 603.2.2, 2021)

The following violations were observed:

Panel N2-H1 circuit space 42 does not have a cover

Life Enrichment Office - broken electrical receptacle cover

3 Relocatable power taps and current taps

Relocatable power taps and current taps. The construction and use of current taps and relocatable power taps shall be in accordance with NFPA 70 and this code.

(IFC 603.5, 2021)

The following violations were observed:

Unproved and/or unfused powerstrips or cubes were in use in the following locations:

Room 231 - two locations
Life enrichment- removed during inspection
Exercise & Yoga Gym
Exercise & Yoga Office/Storage - two locations
Kitchen Managers Office
Room 120 - by door and by television
Training room
Salon- two locations
Executive Director's Office
Director of Nursing Office
Assistant Nurse's Office – two locations
Breakroom – two locations
Reception area- two locations

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name Ciel Senior Living of the Tri-Cities
Address 7255 W GRANDRIDGE BLVD ,
City, State, Zip Kennewick, WA 99336

Provider Number 2449
Approval Status Disapproved
Facility Type Residential Care

On 4/21/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

4 Application and Use

603.5.2 Application and use. Relocatable power taps and current taps shall be directly connected to a permanently installed receptacle.
Exceptions:
1. Where approved for use in a Group A occupancy or in a meeting room in a Group B occupancy, not more than five relocatable power taps shall be permitted to be connected together or connected to an extension cord for temporary use to supply power to electronic equipment.
2. Current taps and relocatable power taps shall not be required to connect directly to a permanently installed receptacle outlet where used for 90 days or less for the purpose of testing the performance of such devices.
(IFC 603.5.2, 2021)

The following violations were observed:

Powerstrips and/or cubes were plugged into another powerstrip or cube in the following locations:
Exercise & Yoga Gym Office/Storage
Director of Nursing Office
Reception area
Salon - two locations

5 Extension Cords

Extension cords. Extension cords shall not be a substitute for permanent wiring and shall be listed and labeled in accordance with UL 817. Extension cords shall not be affixed to structures, extended through walls, ceilings or floors, or under doors or floor coverings, nor shall such cords be subject to environmental damage or physical impact. Extension cords shall be used only with portable appliances. Extension cords marked for indoor use shall not be used outdoors..
(IFC 603.6 2021)

The following violations were observed:

Extension cords were in use in the following locations:
Telecome room near room 212
Salon - two locations

6 Portable, Electric Space Heaters

Where not prohibited by other sections of this code, portable, electric space heaters shall be permitted to be used in all occupancies in accordance with Sections 603.9.1 through 603.9.5.
(IFC 603.9 2021)

The following violation was observed:

Executive Director's Office - portable space heater without tip over protection was in use.

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name Ciel Senior Living of the Tri-Cities
Address 7255 W GRANDRIDGE BLVD ,
City, State, Zip Kennewick, WA 99336

Provider Number 2449
Approval Status Disapproved
Facility Type Residential Care

On 4/21/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

7 Emergency Operation - Elevator Operation, Maint & Fire Service

Existing elevators with a travel distance of 25 feet (7620 mm) or more shall comply with the requirements in Chapter 11. New elevators shall be provided with Phase I emergency recall operation and Phase II emergency in-car operation in accordance with ASME A17.1/CSA B44.

(IFC 604.2, 2021)

The following violation was observed:

Elevator Room - covers for primary recall N1L1M07 and alternate recall N1L1M06 have been removed.

8 Owner's Responsibility

The following violation was observed:

Facility was unable to provide for documentation of annual inspection of the fire-resistance-rated construction within the past twelve months.

9 Penetrations - Maintaining Protection

Materials and firestop systems used to protect membrane and through penetrations in fire-resistance-rated construction and construction installed to resist the passage of smoke shall be maintained. The materials and firestop systems shall be securely attached to or bonded to the construction being penetrated with no openings visible through or into the cavity of the construction. Where the system design number is known, the system shall be inspected to the listing criteria and manufacturer's installation instructions.

(IFC 703.1 2021)

The following violations were observed:

Penetrations in fire-resistance-rated construction were found out in the following places:
Storage by room 313
Fire sprinkler room by room 321
Storage by 325
Telecome by room 225
Storage by 223
Storage by room 113
Denmark Telecome
Storage by room 123
Storage by room 125
Receiving above corridor door

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name Ciel Senior Living of the Tri-Cities
Address 7255 W GRANDRIDGE BLVD ,
City, State, Zip Kennewick, WA 99336

Provider Number 2449
Approval Status Disapproved
Facility Type Residential Care

On 4/21/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

10 Inspection and Maintenance

Opening protectives in fire-resistance-rated assemblies shall be inspected and maintained in accordance with NFPA 80. Opening protectives in smoke barriers shall be inspected and maintained in accordance with NFPA 80 and NFPA 105. Openings in smoke partitions shall be inspected and maintained in accordance with NFPA 105. Fire doors and smoke and draft control doors shall not be blocked, obstructed, or otherwise made inoperable. Fusible links shall be replaced promptly whenever fused or damaged. Opening protectives and smoke and draft control doors shall not be modified.
(IFC 705.2 2021)

The following violation was observed:

Facility was unable to provide documentation of annual rated door inspections within the past twelve months.

11 Hold-Open Devices and Closers

Hold-open devices and automatic door closers, where provided, shall be maintained. During the period that such device is out of service for repairs, the door it operates shall remain in the closed position.
(IFC 705.2.3 2021)

The following violation was observed:

Staff Breakroom in administration corridor - door was blocked open inhibiting self closer

12 Door Operation

Swinging fire doors shall close from the full-open position and latch automatically.
(IFC 705.2.4 2021)

The following violations were observed:

The following fire doors did not latch during testing:
Room 309
Room 231
Cross Corridor by Activity room

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name Ciel Senior Living of the Tri-Cities
Address 7255 W GRANDRIDGE BLVD ,
City, State, Zip Kennewick, WA 99336

Provider Number 2449
Approval Status Disapproved
Facility Type Residential Care

On 4/21/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

13 Duct and Air Transfer Openings - Maintaining Protection

Dampers protecting ducts and air transfer openings shall be inspected and maintained in accordance with NFPA 80 and NFPA 105. Other products or materials used to protect the openings for ducts and air transfer openings shall be securely attached to or bonded to the construction containing the duct or air transfer opening, without visible openings through or into the cavity of the construction. Any damaged products or materials protecting duct and air transfer openings shall be repaired, restored or replaced.

(IFC 706.1 2018)

The following violation was observed:

Facility was unable to provide documentation of inspection and testing of fire/smoke dampers within the past four years.

14 Testing and Maintenance

Sprinkler systems shall be tested and maintained in accordance with Section 901.

(IFC 903.5 2021)

The following violations were observed:

Facility was unable to provide documentation on one of four quarterly inspections of the fire sprinkler system. Facility provided inspections reports for:
June 11, 2024
October 22, 2024
January 20, 2025

Facility was unable to provide documentation of fire sprinkler system internal pipe inspection within the past five years

Kitchen - walk in cooler fire sprinkler head shows visual signs of corrosion

Fire sprinkler heads had excessive dust or particulate on them in the following locations:

Medication Room
Business Office

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name Ciel Senior Living of the Tri-Cities
Address 7255 W GRANDRIDGE BLVD ,
City, State, Zip Kennewick, WA 99336

Provider Number 2449
Approval Status Disapproved
Facility Type Residential Care

On 4/21/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

15 Portable Fire Extinguishers - General Requirements

Portable fire extinguishers shall be selected, installed and maintained in accordance with this section and NFPA 10.

Exceptions:

1. The distance of travel to reach an extinguisher shall not apply. The travel distance to reach an extinguisher shall not apply to the spectator seating portions of Group A-5 occupancies.
2. Thirty-day inspections shall not be required and maintenance shall be allowed to be once every three years for dry-chemical or halogenated agent portable fire extinguishers that are supervised by a listed and approved electronic monitoring device, provided that all of the following conditions are met:
 - 2.1. Electronic monitoring shall confirm that extinguishers are properly positioned, properly charged and unobstructed.
 - 2.2. Loss of power or circuit continuity to the electronic monitoring device shall initiate a trouble signal.
 - 2.3. The extinguishers shall be installed inside of a building or cabinet in a noncorrosive environment.
 - 2.4. Electronic monitoring devices and supervisory circuits shall be tested every 3 years when extinguisher maintenance is performed.
 - 2.5. A written log of required hydrostatic test dates for extinguishers shall be maintained by the owner to verify that hydrostatic tests are conducted at the frequency required by NFPA 10.
3. In Group I-3, portable fire extinguishers shall be permitted to be located at staff locations.

(IFC 906.2 2021)

The following violation was observed:

Fire extinguisher by Room 115 was undercharged

16 Unobstructed and Unobscured

Manual fire alarm boxes shall be provided with ready access, unobstructed, unobscured and visible at all times.

(IFC 907.4.2.6 2021)

The following violation was observed:

Receiving - coffee maker is blocking the manual fire alarm pull station

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name Ciel Senior Living of the Tri-Cities
Address 7255 W GRANDRIDGE BLVD ,
City, State, Zip Kennewick, WA 99336

Provider Number 2449
Approval Status Disapproved
Facility Type Residential Care

On 4/21/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

17 Inspection, Testing and Maintenance

The maintenance and testing schedules and procedures for fire alarm and fire detection systems shall be in accordance with Sections 907.8.1 through 907.8.5 and NFPA 72. Records of inspection, testing and maintenance shall be maintained.

(IFC 907.8 2021)

The following violations were observed:

Upon entry to the facility the fire alarm panel showed the following had been silenced:

System
NAC #1
NAC #2

Staff stated they must clear twice following fire drills after contractor "fried" the panel during last inspection. The facility is working with a contractor to resolve the issue.

Facility was unable to provide documentation of annual fire alarm inspection, testing and maintenance within the past twelve months.

Facility was unable to provide documentation of semi annual fire alarm inspection and testing within the past twelve months.

The following circuit breakers to fire alarm system equipment panel E1-L1 needs a circuit breaker locks:

4
10
12
30
37

Additionally, the circuit breakers shall have a red marking stating "FIRE ALARM CIRCUIT"

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name Ciel Senior Living of the Tri-Cities
Address 7255 W GRANDRIDGE BLVD ,
City, State, Zip Kennewick, WA 99336

Provider Number 2449
Approval Status Disapproved
Facility Type Residential Care

On 4/21/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

18 Smoke Detector Sensitivity

Smoke detector sensitivity shall be checked within one year after installation and every alternate year thereafter. After the second calibration test, where sensitivity tests indicate that the detector has remained within its listed and marked sensitivity range (or 4-percent obscuration light grey smoke, if not marked), the length of time between calibration tests shall be permitted to be extended to a maximum of 5 years. Where the frequency is extended, records of detector-caused nuisance alarms and subsequent trends of these alarms shall be maintained. In zones or areas where nuisance alarms show any increase over the previous year, calibration tests shall be performed.

(IFC 907.8.3 2021)

The following violation was observed:

Facility was unable to provide documentation of smoke detector sensitivity testing within the past five years.

19 Inspection and Maintenance

Fire department connections shall be periodically inspected, tested and maintained in accordance with NFPA 25. Records of inspection, testing and maintenance shall be maintained.

(IFC 912.7 2021)

The following violation was observed:

A deficiency was noted on the July 2024 hydrostatic test report, has not been corrected.

20 Maintenance

Carbon monoxide alarms and carbon monoxide detection systems shall be maintained in accordance with NFPA 72. Carbon monoxide alarms and carbon monoxide detectors that become inoperable or begin producing end-of-life signals shall be replaced.

(IFC 915.6 2021 WAC)

The following violation was observed:

Facility was unable to provided documentation of carbon monoxide alarms testing for the past twelve months.

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name Ciel Senior Living of the Tri-Cities
Address 7255 W GRANDRIDGE BLVD ,
City, State, Zip Kennewick, WA 99336

Provider Number 2449
Approval Status Disapproved
Facility Type Residential Care

On 4/21/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

21 Illumination Level Under Emergency Power

initial illumination that is not less than an average of 1 footcandle (11 lux) and a minimum at any point of 0.1 footcandle(1 lux) measured along the path of egress at floor level. Illumination levels shall be permitted to decline to 0.6 footcandle (6 lux) average and a minimum at any point of 0.06 footcandle (0.6 lux) at the end of the emergency lighting time duration. A maximum-to-minimum illumination uniformity ratio of 40 to 1 shall not be exceeded. In Group I-2 occupancies, failure of a single lamp in a luminaire shall not reduce the illumination level to less than 0.2 foot-candle (2.2 lux).

(IFC 1008.3.5 2021)

The following violations were observed:

Battery-powered emergency lights failed to illuminate when tested in the following locations:
Automatic Transfer Switch Room
Emergency Electrical Room
Elevator Room

22 Maintenance

Emergency and standby power systems shall be maintained in accordance with NFPA 110 and NFPA 111 such that the system is capable of supplying service within the time specified for the type and duration required.

(IFC 1203.4 2021)

The following violation was observed:

Emergency generator documentation provided for April 2, 2024 through November 25, 2024 did not have the meter start and end time recorded on the documents.

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name Ciel Senior Living of the Tri-Cities
Address 7255 W GRANDRIDGE BLVD ,
City, State, Zip Kennewick, WA 99336

Provider Number 2449
Approval Status Disapproved
Facility Type Residential Care

On 4/21/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

23 Securing Compressed Gas Containers, Cylinders and Tanks

Compressed gas containers, cylinders and tanks shall be secured to prevent falling caused by contact, vibration or seismic activity. Securing of compressed gas containers, cylinders and tanks shall be by one of the following methods:

1. Securing containers, cylinders and tanks to a fixed object with one or more restraints.
2. Securing containers, cylinders and tanks on a cart or other mobile device designed for the movement of compressed gas containers, cylinders or tanks.
3. Nesting of compressed gas containers, cylinders and tanks at container filling or servicing facilities or in sellers' warehouses not open to the public. Nesting shall be allowed provided that the nested containers, cylinders or tanks, if dislodged, do not obstruct the required means of egress.
4. Securing of compressed gas containers, cylinders and tanks to or within a rack, framework, cabinet or similar assembly designed for such use.

Exception: Compressed gas containers, cylinders and tanks in the process of examination, filling, transport or servicing.

(IFC 5303.5.3 2021)

The following violations were observed:

The following locations had unsecured compressed gas cylinders:
Kitchen storage
Room 107
Room 114

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name Ciel Senior Living of the Tri-Cities
Address 7255 W GRANDRIDGE BLVD ,
City, State, Zip Kennewick, WA 99336

Provider Number 2449
Approval Status Disapproved
Facility Type Residential Care

On 4/21/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

24 Fire Drills

In all Group I, Group E, and Group R2 Occupancies licensed by the state, at least twelve planned and unannounced fire drills shall be held every year. Drills shall be conducted quarterly on each shift in Group I and Group R2, Occupancies and monthly in Group E Occupancies to familiarize personnel with signals and emergency action required under varied conditions. A detailed written record of all fire drills shall be maintained and available for inspection at all times. When drills are conducted between 9:00 p.m. and 6:00 a.m., a coded announcement may be used instead of audible alarms. Fire drills shall include the transmission of a fire alarm signal and simulation of emergency conditions. The fire alarm monitoring company shall be notified prior to the activation of the fire alarm system for drill purposes and again at the conclusion of the transmission and restoration of the fire alarm system to normal mode.

(WAC 212-12-044)

The following violation was observed:

November 20, 2024 fire drill report did not include location and device used to notify occupants.

Records shall be maintained of required emergency evacuation drills and include the following information:

- 1.. Identity of the person conducting the drill.
2. Date and time of the drill.
3. Notification method used.
4. Employees on duty and participating.
5. Number of occupants evacuated.
6. Special conditions simulated.
7. Problems encountered.
8. Weather conditions when occupants were evacuated.
9. Time required to accomplish complete evacuation.

(IFC 0405.6 2021)

Next inspection scheduled on or after: 5/21/2025

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Authorized Representative

Signature

Print Name and Title

Deputy State Fire Marshal Damon Roberson
2803 156 AVE SE
Bellevue WA 98007
(360) 584-4392

Signature