




Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900


Business Name	The Gardens at Marysville, Independent Living & Al	Provider Number	2476
Address	9802 48th ,	Approval Status	Approved
City, State, Zip	Marysville, WA 98270	Facility Type	Residential Care

On 12/18/2023 the Office of the State Fire Marshal conducted an inspection at your facility.

All violations noted during previous related inspection(s) have been corrected.

Owner or Owner's Representative


Signature


Print Name and Title

Deputy State Fire Marshal Brandon G. Brown
16778 146 ST SE
Monroe WA 98272
(360) 791-7037


Signature

This document was prepared by Residential Care Services for the Locator website.

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	The Gardens at Marysville, Independent Living & AL	Provider Number	2476
Address	9802 48th ,	Approval Status	Disapproved
City, State, Zip	Marysville, WA 98270	Facility Type	Residential Care

On 09/26/2023 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
1 Ceiling Clearance	
Storage shall be maintained 2 feet (610 mm) or more below the ceiling in nonsprinklered areas of buildings or not less than 18 inches (457 mm) below sprinkler head deflectors in sprinklered areas of buildings. Exceptions: 1. The 2-foot (610 mm) ceiling clearance is not required for storage along walls in nonsprinklered areas of buildings. 2. The 18-inch (457 mm) ceiling clearance is not required for storage along walls in areas of buildings equipped with an automatic sprinkler system in accordance with Section 903.3.1.1, 903.3.1.2 or 903.3.1.3. (IFC 315.3.1 2018)	Corrected
2 Unapproved conditions	
Open junction boxes and open-wiring splices shall be prohibited. Approved covers shall be provided for all switch and electrical outlet boxes. (IFC 604.6, 2018)	Corrected
3 Cleaning	
Hoods, grease-removal devices, fans, ducts and other appurtenances shall be cleaned at intervals as required by Sections 607.3.3.1 through 607.3.3.3. (IFC 607.3.3 2018)	Corrected



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name The Gardens at Marysville, Independent Living & AL	Provider Number 2476
Address 9802 48th ,	Approval Status Disapproved
City, State, Zip Marysville, WA 98270	Facility Type Residential Care

On 09/26/2023 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
4 Inspection and Maintenance	
Opening protectives in fire-resistance-rated assemblies shall be inspected and maintained in accordance with NFPA 80. Opening protectives in smoke barriers shall be inspected and maintained in accordance with NFPA 80 and NFPA 105. Openings in smoke partitions shall be inspected and maintained in accordance with NFPA 105. Fire doors and smoke and draft control doors shall not be blocked, obstructed, or otherwise made inoperable. Fusible links shall be replaced promptly whenever fused or damaged. Opening protectives and smoke and draft control doors shall not be modified. (IFC 705.2 2018)	The following violations were observed during the re-inspection: 15 resident room fire doors throughout the facility was blocked open by a various items, preventing it from closing and latching.
5 Door Operation	
Swinging fire doors shall close from the full-open position and latch automatically. (IFC 705.2.4 2018)	The following violations were observed: 1. Resident room #313 fire door would not close and latch from the fully open position. 2. The fire rated door from the 1st floor laundry room to the corridor near memory care would not close and latch from a fully open position.
6 Duct and Air Transfer Openings - Maintaining Protection	
Dampers protecting ducts and air transfer openings shall be inspected and maintained in accordance with NFPA 80 and NFPA 105. Other products or materials used to protect the openings for ducts and air transfer openings shall be securely attached to or bonded to the construction containing the duct or air transfer opening, without visible openings through or into the cavity of the construction. Any damaged products or materials protecting duct and air transfer openings shall be repaired, restored or replaced. (IFC 706.1 2018)	Corrected



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name The Gardens at Marysville, Independent Living & AL **Provider Number** 2476
Address 9802 48th , **Approval Status** Disapproved
City, State, Zip Marysville, WA 98270 **Facility Type** Residential Care

On 09/26/2023 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
7 Testing and Maintenance	
Sprinkler systems shall be tested and maintained in accordance with Section 901. (IFC 903.5 2009, 2012, 2015, 2018)	The following violations were observed: 1. The sprinkler head near room #321 is sagging to low in the ceiling. 2. The sprinkler head near room #313 is sagging to low in the ceiling
8 Unobstructed and Unobscured	
Portable fire extinguishers shall not be obstructed or obscured from view. In rooms or areas in which visual obstruction cannot be completely avoided, means shall be provided to indicate the locations of extinguishers. (IFC 906.6 2015, 2018)	Corrected
9 Inspection, Testing and Maintenance	
The maintenance and testing schedules and procedures for fire alarm and fire detection systems shall be in accordance with Sections 907.8.1 through 907.8.5 and NFPA 72. Records of inspection, testing and maintenance shall be maintained. (IFC 907.8 2018)	Corrected
10 Smoke Detector Sensitivity	
Smoke detector sensitivity shall be checked within one year after installation and every alternate year thereafter. After the second calibration test, where sensitivity tests indicate that the detector has remained within its listed and marked sensitivity range (or 4-percent obscuration light grey smoke, if not marked), the length of time between calibration tests shall be permitted to be extended to a maximum of 5 years. Where the frequency is extended, records of detector-caused nuisance alarms and subsequent trends of these alarms shall be maintained. In zones or areas where nuisance alarms show any increase over the previous year, calibration tests shall be performed. (IFC 907.8.3 2012, 2015, 2018)	Corrected

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name The Gardens at Marysville, Independent Living & AL **Provider Number** 2476
Address 9802 48th , **Approval Status** Disapproved
City, State, Zip Marysville, WA 98270 **Facility Type** Residential Care

On 09/26/2023 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

11 Emergency Power for Illumination - General

In the event of power supply failure in rooms and spaces that require two or more means of egress an emergency electrical system shall automatically illuminate all of the following areas:

1. Aisles
2. Corridors
3. Exit access stairways and ramps

(IFC 1008.3.1 2015, 2018)

The following violations were observed:

The emergency egress light near room 321 would not illuminate when the test button was pressed.

12 Internally Illuminated Exit Signs

Electrically powered, self-luminous and photoluminescent exit signs shall be listed and labeled in accordance with UL 924 and shall be installed in accordance with the manufacturer's instructions and Section 1203. Exit signs shall be illuminated at all times.


(IFC 1013.5 2018)


Corrected

Next inspection scheduled on or after: 10/26/2023

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Authorized Representative


Signature


Print Name and Title

Deputy State Fire Marshal Brandon G. Brown
16778 146 ST SE
Monroe WA 98272
(360) 791-7037


Signature



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	The Gardens at Marysville, Independent Living & AL	Provider Number	2476
Address	9802 48th ,	Approval Status	Disapproved
City, State, Zip	Marysville, WA 98270	Facility Type	Residential Care

On 08/16/2023 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

1 Ceiling Clearance

Storage shall be maintained 2 feet (610 mm) or more below the ceiling in nonsprinklered areas of buildings or not less than 18 inches (457 mm) below sprinkler head deflectors in sprinklered areas of buildings.

Exceptions:

1. The 2-foot (610 mm) ceiling clearance is not required for storage along walls in nonsprinklered areas of buildings.
2. The 18-inch (457 mm) ceiling clearance is not required for storage along walls in areas of buildings equipped with an automatic sprinkler system in accordance with Section 903.3.1.1, 903.3.1.2 or 903.3.1.3.

(IFC 315.3.1 2018)

The following violations were observed:

There is combustible material being stored within 18in of the ceiling in the storage near room #307.

2 Unapproved conditions

Open junction boxes and open-wiring splices shall be prohibited. Approved covers shall be provided for all switch and electrical outlet boxes.

(IFC 604.6, 2018)

The following violations were observed:

There was an electrical outlet without a faceplate in break room, exposing the inner electrical fixture.

3 Cleaning

Hoods, grease-removal devices, fans, ducts and other appurtenances shall be cleaned at intervals as required by Sections 607.3.3.1 through 607.3.3.3.

(IFC 607.3.3 2018)

The following violations were observed:

Facility is unable to provide documentation for the semi-annual hood cleaning.

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	The Gardens at Marysville, Independent Living & AL	Provider Number	2476
Address	9802 48th ,	Approval Status	Disapproved
City, State, Zip	Marysville, WA 98270	Facility Type	Residential Care

On 08/16/2023 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

4 Door Operation

Swinging fire doors shall close from the full-open position and latch automatically.

(IFC 705.2.4 2018)

The following violations were observed:

1. Resident room #313 fire door would not close and latch from the fully open position.
2. The fire rated door from the dining room to the corridor near the kitchen would not close and latch from a fully open position.
3. The fire rated door from the 1st floor laundry room to the corridor near memory care would not close and latch from a fully open position.

5 Duct and Air Transfer Openings - Maintaining Protection

Dampers protecting ducts and air transfer openings shall be inspected and maintained in accordance with NFPA 80 and NFPA 105. Other products or materials used to protect the openings for ducts and air transfer openings shall be securely attached to or bonded to the construction containing the duct or air transfer opening, without visible openings through or into the cavity of the construction. Any damaged products or materials protecting duct and air transfer openings shall be repaired, restored or replaced.

(IFC 706.1 2018)

The following violations were observed:

Facility is unable to provide documentation for the 4 year fire and smoke damper inspection.

6 Testing and Maintenance

Sprinkler systems shall be tested and maintained in accordance with Section 901.

(IFC 903.5 2009, 2012, 2015, 2018)

The following violations were observed:

1. The sprinkler head near room #321 is sagging to low in the ceiling.
2. The sprinkler head near room #313 is sagging to low in the ceiling.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	The Gardens at Marysville, Independent Living & AL	Provider Number	2476
Address	9802 48th ,	Approval Status	Disapproved
City, State, Zip	Marysville, WA 98270	Facility Type	Residential Care

On 08/16/2023 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

7 Unobstructed and Unobscured

Portable fire extinguishers shall not be obstructed or obscured from view. In rooms or areas in which visual obstruction cannot be completely avoided, means shall be provided to indicate the locations of extinguishers.

(IFC 906.6 2015, 2018)

The following violations were observed:

Portable fire extinguisher in Kitchen was obstructed by brooms, mops, and aprons.

8 Inspection, Testing and Maintenance

The maintenance and testing schedules and procedures for fire alarm and fire detection systems shall be in accordance with Sections 907.8.1 through 907.8.5 and NFPA 72. Records of inspection, testing and maintenance shall be maintained.

(IFC 907.8 2018)

The following violations were observed:

The smoke detector head located in the follow areas has been installed within 36 inches of an air supply diffuser or return air opening. This is preventing proper operation of the smoke detector.

1. Beauty shop
2. 3 floor nurses office
3. Activities room

9 Smoke Detector Sensitivity

Smoke detector sensitivity shall be checked within one year after installation and every alternate year thereafter. After the second calibration test, where sensitivity tests indicate that the detector has remained within its listed and marked sensitivity range (or 4-percent obscuration light grey smoke, if not marked), the length of time between calibration tests shall be permitted to be extended to a maximum of 5 years. Where the frequency is extended, records of detector-caused nuisance alarms and subsequent trends of these alarms shall be maintained. In zones or areas where nuisance alarms show any increase over the previous year, calibration tests shall be performed.

(IFC 907.8.3 2012, 2015, 2018)

The following violations were observed:

Facility is unable to provide documentation for the required smoke detector sensitivity testing.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name The Gardens at Marysville, Independent Living & AL **Provider Number** 2476
Address 9802 48th , **Approval Status** Disapproved
City, State, Zip Marysville, WA 98270 **Facility Type** Residential Care

On 08/16/2023 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

10 Emergency Power for Illumination - General

In the event of power supply failure in rooms and spaces that require two or more means of egress an emergency electrical system shall automatically illuminate all of the following areas:

1. Aisles
2. Corridors
3. Exit access stairways and ramps

(IFC 1008.3.1 2015, 2018)

The following violations were observed:

1. The emergency egress light near room 321 would not illuminate when the test button was pressed.
2. Two emergency egress lights near copy room would not illuminate when the test button was pressed.
3. The emergency egress light near fireplace room would not illuminate when the test button was pressed.

11 Internally Illuminated Exit Signs

Electrically powered, self-luminous and photoluminescent exit signs shall be listed and labeled in accordance with UL 924 and shall be installed in accordance with the manufacturer's instructions and Section 1203. Exit signs shall be illuminated at all times.

(IFC 1013.5 2018)

The following violations were observed:


The installed Emergency Exit Sign does not have a secondary power source to ensure continued illumination in case of primary power loss in the following locations.

1. near room #205
2. in 1st floor stairwell B
3. in kitchen

Next inspection scheduled on or after: 09/15/2023

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Authorized Representative


Signature

Scott Martin Maint. Dir.
Print Name and Title

Deputy State Fire Marshal Brandon G. Brown
16778 146 ST SE
Monroe WA 98272
(360) 791-7037


Signature