



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900


Business Name Silverado Bellingham
Address 4400 COLUMBINE DR ,
City, State, Zip Bellingham, WA

Provider Number 2517
Approval Status Approved
Facility Type Residential Care

On 01/15/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

All violations noted during previous related inspection(s) have been corrected.

Owner or Owner's Representative


Signature

Ken Chapell Dir Plant ops
Print Name and Title

Deputy State Fire Marshal Brandon G. Brown
MP 235 SB Interstate 5
Bow WA 98232
(360) 791-7037


Signature

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Silverado Bellingham	Provider Number	2517
Address	4400 COLUMBINE DR ,	Approval Status	Disapproved
City, State, Zip	Bellingham, WA	Facility Type	Residential Care

On 12/03/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

1 Listing

603.5.1 Listing. Relocatable power taps shall be listed in accordance with UL 1363. Current taps shall be listed and labeled in accordance with UL 498A. (IFC 0603.5.1, 2021)	There was multi-plug adapter that what was unable to be verified as listed under UL 498A in the Resident Engagement office.
--	---

2 Cleaning

Hoods, grease-removal devices, fans, ducts and other appurtenances shall be cleaned at intervals as required by Sections 606.3.3.1 through 606.3.3.3. (IFC 606.3.3 2021)	Facility is unable to provide documentation for the 12 months of semi-annual hood cleanings.
---	--

3 Owner's Responsibility

The owner shall maintain an inventory of all required fire-resistance-rated construction, construction installed to resist the passage of smoke and the construction included in Sections 703 through 707 and Sections 602.4.1 and 602.4.2 of the International Building Code. Such construction shall be visually inspected by the owner annually and properly repaired, restored or replaced where damaged, altered, breached or penetrated. Records of inspections and repairs shall be maintained. Where concealed, such elements shall not be required to be visually inspected by the owner unless the concealed space is accessible by the removal or movement of a panel, access door, ceiling tile or similar movable entry to the space. (IFC 701.6 2021)	Facility is unable to provide documentation that the annual fire resistance rated construction material inspection has been completed.
--	--

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name Silverado Bellingham
Address 4400 COLUMBINE DR ,
City, State, Zip Bellingham, WA

Provider Number 2517
Approval Status Disapproved
Facility Type Residential Care

On 12/03/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

4 Inspection and Maintenance

Opening protectives in fire-resistance-rated assemblies shall be inspected and maintained in accordance with NFPA 80. Opening protectives in smoke barriers shall be inspected and maintained in accordance with NFPA 80 and NFPA 105. Openings in smoke partitions shall be inspected and maintained in accordance with NFPA 105. Fire doors and smoke and draft control doors shall not be blocked, obstructed, or otherwise made inoperable. Fusible links shall be replaced promptly whenever fused or damaged. Opening protectives and smoke and draft control doors shall not be modified.

(IFC 705.2 2021)

Facility is unable to provide documentation that the annual fire door inspection has been completed.

5 Testing and Maintenance

Sprinkler systems shall be tested and maintained in accordance with Section 901.

(IFC 903.5 2021)

Facility is unable to provide documentation for the 5 year internal piping inspection.

6 Extinguishing System Service

Automatic fire-extinguishing systems shall be serviced not less frequently than every six months and after activation of the system. Inspection shall be by qualified individuals, and a certificate of inspection shall be forwarded to the fire code official upon completion.

(IFC 904.13.5.2 2021)

The UL 300 complaint kitchen suppression system has 450 degree fusible links currently installed with no evidence of a proper heat test in accordance manufactures instructions.

7 Inspection, Testing and Maintenance

The maintenance and testing schedules and procedures for fire alarm and fire detection systems shall be in accordance with Sections 907.8.1 through 907.8.5 and NFPA 72. Records of inspection, testing and maintenance shall be maintained.

(IFC 907.8 2021)

1. Facility is unable to provide documentation for the monthly single station smoke alarm testing.
2. The power breaker #3 in panel IC2 for the fire alarm system is missing locking device.

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name Silverado Bellingham
Address 4400 COLUMBINE DR ,
City, State, Zip Bellingham, WA

Provider Number 2517
Approval Status Disapproved
Facility Type Residential Care

On 12/03/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

8 Maintenance

Carbon monoxide alarms and carbon monoxide detection systems shall be maintained in accordance with NFPA 72. Carbon monoxide alarms and carbon monoxide detectors that become inoperable or begin producing end-of-life signals shall be replaced.

(IFC 915.6 2021 WAC)

Facility is unable to provide documentation for the monthly carbon monoxide detector testing.

9 Maintenance

Emergency and standby power systems shall be maintained in accordance with NFPA 110 and NFPA 111 such that the system is capable of supplying service within the time specified for the type and duration required.

(IFC 1203.4 2021)

1. Facility is unable to provide documentation for the annual servicing of the emergency generator.


2. Facility is unable to provide documentation for the weekly inspections and Monthly 30 minute full load testing.


3. Facility is unable to provide documentation showing that a fuel quality test has been performed within the past 12 months.

Next inspection scheduled on or after: 01/02/2026


Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Authorized Representative


Signature

 
Print Name and Title

Deputy State Fire Marshal Brandon G. Brown
MP 235 SB Interstate 5
Bow WA 98232
(360) 791-7037


Signature