



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Brookdale Fairhaven	Provider Number	2525
Address	2600 OLD FAIRHAVEN PKWY ,	Approval Status	Approved
City, State, Zip	Bellingham, WA 98225	Facility Type	Residential Care

On 10/22/2024 the Office of the State Fire Marshal conducted an inspection at your facility.

All violations noted during previous related inspection(s) have been corrected.

Owner or Owner's Representative

Tou Mays
Signature

Tou Mays Executive Director
Print Name and Title

Deputy State Fire Marshal Brandon G. Brown
16778 146 ST SE
Monroe WA 98272
(360) 791-7037

[Signature]
Signature

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name Brookdale Fairhaven	Provider Number 2525
Address 2600 OLD FAIRHAVEN PKWY ,	Approval Status Disapproved
City, State, Zip Bellingham, WA 98225	Facility Type Residential Care

On 05/29/2024 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

1 Door Operation

Swinging fire doors shall close from the full-open position and latch automatically. (IFC 705.2.4 2021)	Corrected
--	-----------

2 Testing and Maintenance

Sprinkler systems shall be tested and maintained in accordance with Section 901. (IFC 903.5 2021)	As per documents provided the sprinkler system had deficiencies noted that have not been corrected. Update: 10 year and 20 year sprinkler head testing has not been completed.
--	---

3 Smoke Detector Sensitivity

Smoke detector sensitivity shall be checked within one year after installation and every alternate year thereafter. After the second calibration test, where sensitivity tests indicate that the detector has remained within its listed and marked sensitivity range (or 4-percent obscuration light grey smoke, if not marked), the length of time between calibration tests shall be permitted to be extended to a maximum of 5 years. Where the frequency is extended, records of detector-caused nuisance alarms and subsequent trends of these alarms shall be maintained. In zones or areas where nuisance alarms show any increase over the previous year, calibration tests shall be performed. (IFC 907.8.3 2021)	Facility is unable to provide documentation for the required smoke detector sensitivity testing. NOTE: A nuisance log is not being maintained. Update: Sensitivity test was completed 4/9/24. Failed smoke detectors have not been replaced.
--	--

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Brookdale Fairhaven	Provider Number	2525
Address	2600 OLD FAIRHAVEN PKWY ,	Approval Status	Disapproved
City, State, Zip	Bellingham, WA 98225	Facility Type	Residential Care

On 05/29/2024 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

Next inspection scheduled on or after: 06/28/2024

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Authorized Representative

Signature

Print Name and Title

Deputy State Fire Marshal Brandon G. Brown
16778 146 ST SE
Monroe WA 98272
(360) 791-7037

Signature

Initials of Authorized Facility Representative: _____



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Brookdale Fairhaven	Provider Number	2525
Address	2600 OLD FAIRHAVEN PKWY ,	Approval Status	Disapproved
City, State, Zip	Bellingham, WA 98225	Facility Type	Residential Care

On 04/24/2024 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

1 Listing

603.5.1 Listing. Relocatable power taps shall be listed in accordance with UL 1363. Current taps shall be listed and labeled in accordance with UL 498A.

(IFC 0603.5.1, 2021)

Corrected

2 Door Operation

Swinging fire doors shall close from the full-open position and latch automatically.

(IFC 705.2.4 2021)

The fire rated door from the dining room to the corridor would not close and latch from a fully open position.

3 Testing and Maintenance

Sprinkler systems shall be tested and maintained in accordance with Section 901.

(IFC 903.5 2021)

1. As per documents provided the sprinkler system had deficiencies noted that have not been corrected.

2. There was a sprinkler head in the kitchen that is loaded with combustible materials (lint).

4 Smoke Detector Sensitivity

Smoke detector sensitivity shall be checked within one year after installation and every alternate year thereafter. After the second calibration test, where sensitivity tests indicate that the detector has remained within its listed and marked sensitivity range (or 4-percent obscuration light grey smoke, if not marked), the length of time between calibration tests shall be permitted to be extended to a maximum of 5 years. Where the frequency is extended, records of detector-caused nuisance alarms and subsequent trends of these alarms shall be maintained. In zones or areas where nuisance alarms show any increase over the previous year, calibration tests shall be performed.

(IFC 907.8.3 2021)

Facility is unable to provide documentation for the required smoke detector sensitivity testing.

NOTE: A nuisance log is not being maintained.

Update: Sensitivity test was completed 4/9/24 and 70 of 83 failed. Facility is planning on replacing all 83.

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Brookdale Fairhaven	Provider Number	2525
Address	2600 OLD FAIRHAVEN PKWY ,	Approval Status	Disapproved
City, State, Zip	Bellingham, WA 98225	Facility Type	Residential Care

On 04/24/2024 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

5 Unlatching

The unlatching of any door or leaf for egress shall require not more than one motion in a single linear or rotational direction to release all latching and all locking devices. Exceptions: 1. Places of detention or restraint. 2. Where manually operated bolt locks are permitted by Section 1010.2.5. 3. Doors with automatic flush bolts as permitted by Section 1010.2.4, Item 4. 4. Doors from individual dwelling units and sleeping units of Group R occupancies as permitted by Section 1010.2.4, Item 5. (IFC 1010.2.1 2021)	Corrected
--	-----------

Next inspection scheduled on or after: 05/24/2024


Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Authorized Representative


Signature

 E.D.
Print Name and Title

Deputy State Fire Marshal Brandon G. Brown
16778 146 ST SE
Monroe WA 98272
(360) 791-7037


Signature



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Brookdale Fairhaven	Provider Number	2525
Address	2600 OLD FAIRHAVEN PKWY ,	Approval Status	Disapproved
City, State, Zip	Bellingham, WA 98225	Facility Type	Residential Care

On 03/21/2024 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

1 Listing

603.5.1 Listing. Relocatable power taps shall be listed in accordance with UL 1363. Current taps shall be listed and labeled in accordance with UL 498A. (IFC 0603.5.1, 2021)	There was two multi-plug adapters that does not have over current protection in use in room 59.
--	---

2 Door Operation

Swinging fire doors shall close from the full-open position and latch automatically. (IFC 705.2.4 2021)	The fire rated door from the dining room to the corridor would not close and latch from a fully open position.
--	--

3 Testing and Maintenance

Sprinkler systems shall be tested and maintained in accordance with Section 901. (IFC 903.5 2021)	1. As per documents provided the sprinkler system had deficiencies noted that have not been corrected. 2. There was a sprinkler head in the kitchen that is loaded with combustible materials (lint).
--	--

4 Smoke Detector Sensitivity

Smoke detector sensitivity shall be checked within one year after installation and every alternate year thereafter. After the second calibration test, where sensitivity tests indicate that the detector has remained within its listed and marked sensitivity range (or 4-percent obscuration light grey smoke, if not marked), the length of time between calibration tests shall be permitted to be extended to a maximum of 5 years. Where the frequency is extended, records of detector-caused nuisance alarms and subsequent trends of these alarms shall be maintained. In zones or areas where nuisance alarms show any increase over the previous year, calibration tests shall be performed. (IFC 907.8.3 2021)	Facility is unable to provide documentation for the required smoke detector sensitivity testing. NOTE: A nuisance log is not being maintained.
--	---

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Brookdale Fairhaven	Provider Number	2525
Address	2600 OLD FAIRHAVEN PKWY ,	Approval Status	Disapproved
City, State, Zip	Bellingham, WA 98225	Facility Type	Residential Care

On 03/21/2024 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

5 Unlatching

The unlatching of any door or leaf for egress shall require not more than one motion in a single linear or rotational direction to release all latching and all locking devices.

Exceptions:

1. Places of detention or restraint.
2. Where manually operated bolt locks are permitted by Section 1010.2.5.
3. Doors with automatic flush bolts as permitted by Section 1010.2.4, Item 4.
4. Doors from individual dwelling units and sleeping units of Group R occupancies as permitted by Section 1010.2.4, Item 5.

(IFC 1010.2.1 2021)

Emergency exit door in the kitchen has a locking devices which requires double action to open.

Next inspection scheduled on or after: 04/20/2024

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Authorized Representative

Signature

Print Name and Title **Ted Margeson E.O.**

Deputy State Fire Marshal Brandon G. Brown
16778 146 ST SE
Monroe WA 98272
(360) 791-7037

Signature