




Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Woodway Senior Living	Provider Number	2563
Address	1712 E MAPLEWOOD AVE ,	Approval Status	Approved
City, State, Zip	Bellingham, WA 98225	Facility Type	Residential Care

On 04/07/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

All violations noted during previous related inspection(s) have been corrected.

Owner or Owner's Representative


Signature


Print Name and Title

Deputy State Fire Marshal Brandon G. Brown
16778 146 ST SE
Monroe WA 98272
(360) 791-7037


Signature

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Woodway Senior Living	Provider Number	2563
Address	1712 E MAPLEWOOD AVE ,	Approval Status	Disapproved
City, State, Zip	Bellingham, WA 98225	Facility Type	Residential Care

On 03/04/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

1 Owner's Responsibility

The owner shall maintain an inventory of all required fire-resistance-rated construction, construction installed to resist the passage of smoke and the construction included in Sections 703 through 707 and Sections 602.4.1 and 602.4.2 of the International Building Code. Such construction shall be visually inspected by the owner annually and properly repaired, restored or replaced where damaged, altered, breached or penetrated. Records of inspections and repairs shall be maintained. Where concealed, such elements shall not be required to be visually inspected by the owner unless the concealed space is accessible by the removal or movement of a panel, access door, ceiling tile or similar movable entry to the space. (IFC 701.6 2021)	Facility is unable to provide documentation that the annual fire resistance rated construction material inspection has been completed.
---	---

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Woodway Senior Living	Provider Number	2563
Address	1712 E MAPLEWOOD AVE ,	Approval Status	Disapproved
City, State, Zip	Bellingham, WA 98225	Facility Type	Residential Care

On 03/04/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

2 Unobstructed and Unobscured

Portable fire extinguishers shall be selected, installed and maintained in accordance with this section and NFPA 10.

Exceptions:

1. The distance of travel to reach an extinguisher shall not apply. The travel distance to reach an extinguisher shall not apply to the spectator seating portions of Group A-5 occupancies.
2. Thirty-day inspections shall not be required and maintenance shall be allowed to be once every three years for dry-chemical or halogenated agent portable fire extinguishers that are supervised by a listed and approved electronic monitoring device, provided that all of the following conditions are met:
 - 2.1. Electronic monitoring shall confirm that extinguishers are properly positioned, properly charged and unobstructed.
 - 2.2. Loss of power or circuit continuity to the electronic monitoring device shall initiate a trouble signal.
 - 2.3. The extinguishers shall be installed inside of a building or cabinet in a noncorrosive environment.
 - 2.4. Electronic monitoring devices and supervisory circuits shall be tested every 3 years when extinguisher maintenance is performed.
 - 2.5. A written log of required hydrostatic test dates for extinguishers shall be maintained by the owner to verify that hydrostatic tests are conducted at the frequency required by NFPA 10.
3. In Group I-3, portable fire extinguishers shall be permitted to be located at staff locations.

(IFC 906.2 2021)

Portable fire extinguisher near 302 was obstructed by carts.

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Woodway Senior Living	Provider Number	2563
Address	1712 E MAPLEWOOD AVE ,	Approval Status	Disapproved
City, State, Zip	Bellingham, WA 98225	Facility Type	Residential Care

On 03/04/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

3 Smoke Detector Sensitivity

Smoke detector sensitivity shall be checked within one year after installation and every alternate year thereafter. After the second calibration test, where sensitivity tests indicate that the detector has remained within its listed and marked sensitivity range (or 4-percent obscuration light grey smoke, if not marked), the length of time between calibration tests shall be permitted to be extended to a maximum of 5 years. Where the frequency is extended, records of detector-caused nuisance alarms and subsequent trends of these alarms shall be maintained. In zones or areas where nuisance alarms show any increase over the previous year, calibration tests shall be performed. (IFC 907.8.3 2021)	Facility is unable to provide documentation for the required smoke detector sensitivity testing.
--	--

4 Inspection and Maintenance

Fire department connections shall be periodically inspected, tested and maintained in accordance with NFPA 25. Records of inspection, testing and maintenance shall be maintained. (IFC 912.7 2021)	Facility was unable to provide documentation that the Fire Department Connection has been hydrostatically tested in accordance with NFPA 25.
--	--

5 Maintenance

Carbon monoxide alarms and carbon monoxide detection systems shall be maintained in accordance with NFPA 72. Carbon monoxide alarms and carbon monoxide detectors that become inoperable or begin producing end-of-life signals shall be replaced. (IFC 915.6 2021 WAC)	Facility is unable to provide documentation for the monthly carbon monoxide detector testing. Missing documents for Feb 25, Nov 24, Aug 24, Jul 24, Jun 24, Mar 24.
--	---

6 Emergency Power for Illumination - General

In the event of power supply failure in rooms and spaces that require two or more exits or access to exits, an emergency electrical system shall automatically illuminate all of the following areas: 1. Aisles 2. Corridors 3. Exit access stairways and ramps (IFC 1008.3.1 2021)	The emergency egress light in the northwest stairwell would not illuminate when the test button was pressed.
---	--



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Woodway Senior Living	Provider Number	2563
Address	1712 E MAPLEWOOD AVE ,	Approval Status	Disapproved
City, State, Zip	Bellingham, WA 98225	Facility Type	Residential Care

On 03/04/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

7 Internally Illuminated Exit Signs

Electrically powered, self-luminous and photoluminescent exit signs shall be listed and labeled in accordance with UL 924 and shall be installed in accordance with the manufacturer's instructions and Section 1203. Exit signs shall be illuminated at all times. (IFC 1013.5 2021)	1. Multiple exit signs on the 1st floor have broken test buttons. 2. The internally illuminated exit sign near the stairs in the dining room was not illuminated on normal power.
--	--

8 Activation Test

Emergency lighting equipment shall be tested monthly for a duration of not less than 30 seconds. The test shall be performed manually or by an automated self-testing and self-diagnostic routine. Where testing is performed by self-testing and self-diagnostics, a visual inspection of the emergency lighting equipment shall be conducted monthly to identify any equipment displaying a trouble indicator or that has become damaged or otherwise impaired. (IFC 1032.10.1 2021)	Facility is unable to provide documentation for the monthly 30 second activation test for the emergency lights. Missing documents for Feb 25, Nov 24, Aug 24, Jul 24, Jun, 24, Mar 24.
---	--

9 Power Test

Battery-powered emergency lighting equipment shall be tested annually by operating the equipment on battery power for not less than 90 minutes. (IFC 1031.10.2 2021)	Facility is unable to provide documentation for the annual 90 minute power test for the emergency lights.
---	---

10 Fire Drills

In all Group I, Group E, and Group R2 Occupancies licensed by the state and inspected by the state fire marshal's office, at least twelve planned and unannounced fire drills shall be held every year. (1) Drills shall be conducted quarterly on each shift in Group I and Group R2, Occupancies and monthly in Group E Occupancies to familiarize personnel with signals and emergency action required under varied conditions. (2) A detailed written record of all fire drills shall be maintained and available for inspection. (3) When drills are conducted between 9:00 p.m. and 6:00 a.m., a coded announcement may be used instead of audible alarms.	Facility cannot provide documentation for the completion of twelve planned and unannounced fire drills in the previous 12 months. The following Drills are missing. 1st Shift - Quarter 1 and 2 2nd Shift - Quarter 1, 2, 3, and 4 3rd Shift - Quarter 1, 2, 3, and 4
---	---



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Woodway Senior Living	Provider Number	2563
Address	1712 E MAPLEWOOD AVE ,	Approval Status	Disapproved
City, State, Zip	Bellingham, WA 98225	Facility Type	Residential Care

On 03/04/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

Next inspection scheduled on or after: 04/03/2025

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Authorized Representative


Signature

Frank Kereker, WAFO, Director
Print Name and Title

Deputy State Fire Marshal Brandon G. Brown
16778 146 ST SE
Monroe WA 98272
(360) 791-7037


Signature

This document was prepared by Residential Care Services for the Locator website.