




Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Avista Senior Living Ferndale (Louisa Place)	Provider Number	2677
Address	2240 MAIN ST ,	Approval Status	Approved
City, State, Zip	Ferndale, WA	Facility Type	Residential Care

On 10/29/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

All violations noted during previous related inspection(s) have been corrected.

Owner or Owner's Representative


Signature

Santa Gerz Maint.
Print Name and Title Director

Deputy State Fire Marshal Brandon G. Brown
MP 235 SB Interstate 5
Bow WA 98232
(360) 791-7037


Signature

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Avista Senior Living Ferndale (Louisa Place)	Provider Number	2677
Address	2240 MAIN ST ,	Approval Status	Disapproved
City, State, Zip	Ferndale, WA	Facility Type	Residential Care

On 09/15/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

1 Smoking General

The smoking or carrying of a lighted pipe, cigar, cigarette or any other type of smoking paraphernalia or material is prohibited in the areas indicated in Sections 310.2 through 310.8.

(IFC 310.1 2015, 2018)

1. Resident smoking within 25 feet from the main entry.
2. Kitchen staff smoking within 25 feet from the kitchen entry.

2 Application and Use

603.5.2 Application and use. Relocatable power taps and current taps shall be directly connected to a permanently installed receptacle.

Exceptions:

1. Where approved for use in a Group A occupancy or in a meeting room in a Group B occupancy, not more than five relocatable power taps shall be permitted to be connected together or connected to an extension cord for temporary use to supply power to electronic equipment.
2. Current taps and relocatable power taps shall not be required to connect directly to a permanently installed receptacle outlet where used for 90 days or less for the purpose of testing the performance of such devices.

(IFC 603.5.2, 2021)

1. There is a power strip plugged into another power strip in the living room.
2. There is a power strip plugged into another power strip in room 135

3 Extension Cords

Extension cords. Extension cords shall not be a substitute for permanent wiring and shall be listed and labeled in accordance with UL 817. Extension cords shall not be affixed to structures, extended through walls, ceilings or floors, or under doors or floor coverings, nor shall such cords be subject to environmental damage or physical impact. Extension cords shall be used only with portable appliances. Extension cords marked for indoor use shall not be used outdoors..

(IFC 603.6 2021)

There was an extension cord utilized as permanent wiring in room 107.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name Avista Senior Living Ferndale (Louisa Place)
Address 2240 MAIN ST ,
City, State, Zip Ferndale, WA

Provider Number 2677
Approval Status Disapproved
Facility Type Residential Care

On 09/15/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

4 Testing and Maintenance

Sprinkler systems shall be tested and maintained in accordance with Section 901.

(IFC 903.5 2021)

1. The hydraulic calculation placard is missing from the dry sprinkler system.
2. There was two missing escutcheon plates from the sprinkler located in the outside furnace room near 123.
3. There was a missing escutcheon plate from the sprinkler located in the outside electrical room.
4. Facility is unable to provide documentation for the annual forward flow test in accordance with NFPA 25.

5 Hangers and Brackets

Hand-held portable fire extinguishers, not housed in cabinets, shall be installed on the hangers or brackets supplied. Hangers or brackets shall be securely anchored to the mounting surface in accordance with the manufacturer's installation instructions.

(IFC 906.7 2021)

The K-type in the kitchen is not mounted within 30 feet of the appliances. Extinguisher is sitting on the floor.

6 Inspection, Testing and Maintenance

The maintenance and testing schedules and procedures for fire alarm and fire detection systems shall be in accordance with Sections 907.8.1 through 907.8.5 and NFPA 72. Records of inspection, testing and maintenance shall be maintained.

(IFC 907.8 2021)

The power breaker #23 in panel X for the fire alarm system is missing locking device.

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Avista Senior Living Ferndale (Louisa Place)	Provider Number	2677
Address	2240 MAIN ST ,	Approval Status	Disapproved
City, State, Zip	Ferndale, WA	Facility Type	Residential Care

On 09/15/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

Next inspection scheduled on or after: 10/15/2025

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Owner's Representative


Signature

Santas Gerza Mant.
Print Name and Title Manager

Deputy State Fire Marshal Brandon G. Brown
MP 235 SB Interstate 5
Bow WA 98232
(360) 791-7037


Signature

This document was prepared by Residential Care Services for the Locator website.