



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Lake Whatcom Residential & Treatment Ctr.	Provider Number	000601
Address	3400 AGATE HEIGHTS RD ,	Approval Status	Approved
City, State, Zip	Bellingham, WA 98226	Facility Type	Residential Care

On 03/26/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

All violations noted during previous related inspection(s) have been corrected.

Owner or Owner's Representative


Signature

Linda Dunn Clinical Supervisor
Print Name and Title

Deputy State Fire Marshal Brandon G. Brown
16778 146 ST SE
Monroe WA 98272
(360) 791-7037


Signature

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Lake Whatcom Residential & Treatment Ctr.	Provider Number	000601
Address	3400 AGATE HEIGHTS RD.	Approval Status	Disapproved
City, State, Zip	Bellingham, WA 98226	Facility Type	Residential Care

On 03/06/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

1 Portable Fire Extinguishers - General Requirements

Portable fire extinguishers shall be selected, installed and maintained in accordance with this section and NFPA 10.

Exceptions:

1. The distance of travel to reach an extinguisher shall not apply. The travel distance to reach an extinguisher shall not apply to the spectator seating portions of Group A-5 occupancies.

2. Thirty-day inspections shall not be required and maintenance shall be allowed to be once every three years for dry-chemical or halogenated agent portable fire extinguishers that are supervised by a listed and approved electronic monitoring device, provided that all of the following conditions are met:

2.1. Electronic monitoring shall confirm that extinguishers are properly positioned, properly charged and unobstructed.

2.2. Loss of power or circuit continuity to the electronic monitoring device shall initiate a trouble signal.

2.3. The extinguishers shall be installed inside of a building or cabinet in a noncorrosive environment.

2.4. Electronic monitoring devices and supervisory circuits shall be tested every 3 years when extinguisher maintenance is performed.

2.5. A written log of required hydrostatic test dates for extinguishers shall be maintained by the owner to verify that hydrostatic tests are conducted at the frequency required by NFPA 10.

3. In Group I-3, portable fire extinguishers shall be permitted to be located at staff locations.

(IFC 906.2 2021)

1. The required annual maintenance for the fire extinguisher in the mechanical room near 210 has not been completed in accordance with NFPA 10

2. The required annual maintenance for the fire extinguisher in the boiler room near entry has not been completed in accordance with NFPA 10

3. The required annual maintenance for the fire extinguisher in the boiler room near sprinkler riser has not been completed in accordance with NFPA 10

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Lake Whatcom Residential & Treatment Ctr.	Provider Number	000601
Address	3400 AGATE HEIGHTS RD ,	Approval Status	Disapproved
City, State, Zip	Bellingham, WA 98226	Facility Type	Residential Care

On 03/06/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

2 Hangers and Brackets

Hand-held portable fire extinguishers, not housed in cabinets, shall be installed on the hangers or brackets supplied. Hangers or brackets shall be securely anchored to the mounting surface in accordance with the manufacturer's installation instructions.
(IFC 906.7 2021)

1. Fire Extinguisher in the kitchen is on the floor and not mounted in accordance with the manufacturer's installation instructions.
2. Fire Extinguisher in the basement kitchen is hanging on a coat hanger and not mounted in accordance with the manufacturer's installation instructions.

3 Extinguishers Weighing 40 Pounds or Less

Portable fire extinguishers having a gross weight not exceeding 40 pounds (18 kg) shall be installed so that their tops are not more than 5 feet (1524 mm) above the floor.
(IFC 906.9.1 2021)

1. There was a fire extinguisher mounted in the main laundry with its handle more than five feet above the finished floor.
2. There was a fire extinguisher mounted in the resident laundry with its handle more than five feet above the finished floor.
3. There was a fire extinguisher mounted in the basement kitchen with its handle more than five feet above the finished floor.

Next inspection scheduled on or after: 04/05/2025


Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Authorized Representative


Signature

Linda Dunn Clinical Supervisor
Print Name and Title

Deputy State Fire Marshal Brandon G. Brown
16778 146 ST SE
Monroe WA 98272
(360) 791-7037


Signature