

Healthcare Licensing and Surveys

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: WY9055	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING: _____	(X3) DATE SURVEY COMPLETED R 07/07/2023
NAME OF PROVIDER OR SUPPLIER EVERGREEN PLAZA ASSISTED LIVING		STREET ADDRESS, CITY, STATE, ZIP CODE 536 EAST 20TH AVENUE TORRINGTON, WY 82240		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{S 000}	General Comments A Life Safety Code Revisit Survey was conducted by Healthcare Licensing and Surveys on 7/7/2023, for all previous deficiencies identified on 05/09/2023. All deficiencies have been corrected. The facility is now back in compliance.	{S 000}		

Wyoming Dept of Health, Aging Division, Healthcare Licensing and Surveys
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

STATE FORM

0299

YREV12

If continuation sheet 1 of 1