

Healthcare Licensing and Surveys

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: ALF008	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING: _____	(X3) DATE SURVEY COMPLETED R 06/07/2024
--	--	--	---

NAME OF PROVIDER OR SUPPLIER SIERRA HILLS ASSISTED LIVING COMMUNITY	STREET ADDRESS, CITY, STATE, ZIP CODE 4606 NORTH COLLEGE DRIVE CHEYENNE, WY 82009
--	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{S 000}	General Comments A Life Safety Code Complaint revisit survey was conducted by Healthcare Licensing and Surveys on 6/7/2024 for all previous deficiencies identified on 4/6/2024. The facility was not found to be in compliance with two deficiencies previously identified still existing.	{S 000}		
{S8027}	NFPA Life Safety - Nfpa Emergency Egress & Rel Dr NFPA 101 Emergency Egress and Relocation Drills This State Rule and Regulation is not met as evidenced by: Based on document review and staff interview, the facility failed to conduct fire exit drills in accordance with NFPA 101, Life Safety Code and Wyoming Department of Health (WDH) Chapter 12 Rules, Program Administration for Assisted Living Facilities. Failure to conduct fire exit drills as required could result in delayed egress during an emergency leading to injury or death. The deficiency could potentially affect all residents, staff, and visitors. The findings were: 1. Document review on 6/7/2024 starting at 9:00 AM revealed the facility had only been exercising one wing of the facility per drill, while instructing other residents to remain in their rooms and close the doors. This is according to the facilities written fire drill instructions to staff. NFPA 101 states that drills shall involve the actual evacuation of all residents to an assembly point. Residents that cannot meaningfully assist in their own evacuation, or who have special health problems, shall not be required to actively participate in the drill. Section 18.7 shall apply in such instances for those residents. Residents that require	{S8027}		

Wyoming Dept of Health, Aging Division, Healthcare Licensing and Surveys
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

STATE FORM

0600

0E4K12

If continuation sheet 1 of 2

This POC is accepted on 7/5/24 via email to the ED.

[Signature]

Healthcare Licensing and Surveys

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: ALF008	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING: _____		(X3) DATE SURVEY COMPLETED R 06/07/2024
NAME OF PROVIDER OR SUPPLIER SIERRA HILLS ASSISTED LIVING COMMUNITY		STREET ADDRESS, CITY, STATE, ZIP CODE 4606 NORTH COLLEGE DRIVE CHEYENNE, WY 82009			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETE DATE
{S8027}	Continued From page 1 assistance shall be indicated in the facility's Evacuation and Relocation plan. Document review did not demonstrate that the facility's plan contained such language. Interview with the administrator at the time of exit confirmed the deficiency. Ref: 1994 NFPA 101, Ch. 22 Sec. 3.5, Ch. 31 Sec. 1.5 2. Document review on 6/7/2024 starting at 9:00 AM revealed the facility did not demonstrate they provided a contract for outside hospice services identifying the clear delineation of services pertaining to Life Safety Code responsibilities. Interview with the administrator at the time of exit confirmed the deficiency. Ref: WDH Chapter 12, Sec. 9 (a)(ii)	{S8027}			

Sierra Hills Assisted Living Community


Survey Date : 6/7/2024

Ref : LH-2024-0588

S8027

1. The ED and the ESD will hold an evacuation that involves all wings of the facility. The ED and ESD will conduct this drill no later than 7/30/2024 and have complete and accurate documentation of the drill and evacuation of residents.
2. The ED and CSD will work with Caring Edge Hospice to provide a contract for outside hospice services identifying the clear delineation of services pertaining to Life Safety Code responsibilities by 7/30/2024.

Chasnee Schaefer



Executive Director