

**AGENCY FOR HEALTH CARE
ADMINISTRATION**

PRINTED: 02/05/2019
FORM APPROVED

STATEMENT OF DEFICIENCIES	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: AL11964817	(X3) DATE SURVEY COMPLETED 01/09/2019
NAME OF PROVIDER OR SUPPLIER ARDEN COURTS OF LELY PALMS	STREET ADDRESS, CITY, STATE, ZIP CODE 6125 RATTLESNAKE HAMMOCK ROAD NAPLES, FL 34113	
SUMMARY STATEMENT OF DEFICIENCIES (FINDINGS PRECEDED BY TAGS AND REGULATORY IDENTIFYING INFORMATION)		
0000 - Initial Comments An unannounced emergency power plan monitoring survey was conducted on at Arden Courts of Lely Palms, an assisted living facility (license #9326) in Naples, Florida. The following is description of the deficiency. 0200 - Emergency Environmental Control - 58A-5.036 FAC Based on staff interview and observation, the facility failed to have monoxide detectors in their facility. The findings included: Observation of the facility generator on revealed no monoxide detectors in the facility. During an interview with the Administrator on at 1:00 p.m., she reported she did not have monoxide detectors in the facility Class III		