

920934

PRINTED: 11/01/2016
FORM APPROVED

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL017040	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 10/20/2016
---	--	---	---

NAME OF PROVIDER OR SUPPLIER

STREET ADDRESS, CITY, STATE, ZIP CODE

G ANTHONY RUCKER REST HOME

1196 HODGES DAIRY ROAD
YANCEYVILLE, NC 27379

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	Initial Comments Report of a Biennial Construction Survey by Frank Strickland on 10/20/2016: This facility was licensed on 11/07/1998 as a Home for the Aged serving twelve residents. Therefore, this facility must meet the 1984 and the applicable portions of the 2005 Rules for the Licensing of Adult Care Homes, and, the 1978 North Carolina State Building Code with 1984 revision section 409.1(c) Institutional (I) Occupancy- Unrestrained in effect at the time of initial licensure. Deficiencies were cited and a Plan of Correction is required.	C 000		
C 164	Housekeeping and Furnishings-Clean, Repaired SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS (a) Adult care homes shall: (1) have walls, ceilings, and floors or floor coverings kept clean and in good repair; (2) have no chronic unpleasant odors; (3) have furniture clean and in good repair; (e) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: 1-Based on observations, this facility has failed to maintain the interior surfaces of interior doors. Findings on 10/20/2016: The following interior door faces have finishes that are scratched and marked-up due to wheel-chair collisions: (a) Exterior exit door that leads to Courtyard. (b) Bedroom #1	C 164	CONSTRUCTION SECTION NOV 8 2016 RECEIVED Administrator will assure that exit door leading to Courtyard and bedroom #1 doors scratches be repair and fixed.	11/20

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE -

(X6) DATE

Gentry L. Rucker

STATE FORM

11/19/16

Administrator

KKPS21

If continuation sheet 1 of 2

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL017040	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 10/20/2016
NAME OF PROVIDER OR SUPPLIER G ANTHONY RUCKER REST HOME		STREET ADDRESS, CITY, STATE, ZIP CODE 1196 HODGES DAIRY ROAD YANCEYVILLE, NC 27379		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 164	Continued From page 1 2-Based on observations, this facility has failed to maintain the exterior wood trim finishes. Findings on 10/20/2016: The front entry roof wood fascia boards have peeling paint and are unsecured to the roof structure.	C 164	Administrator will assure that peeling paint on board entry roof will be painted and tacked back to the structure.	11/20
C 166	Housekeeping-Maintained Free of Hazards SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS (a) Adult care homes shall: (5) be maintained in an uncluttered, clean and orderly manner, free of all obstructions and hazards; (e) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: 1-Based on observation, the facility has not maintained in a safe manner by improper storage of oxygen cylinders. This could affect all residents and staff by potentially exposing them to hazards for a ruptured ruptured cylinder. Findings on 10/20/2016: There are 4 oxygen bottles in the corner of the Soiled Linen Closet that are not in racks.	C 166	Administrator will assure that all oxygen tanks in hall closet be removed from hall closet	11/20