




Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Creekside Continuing Care Community	Provider Number	2316
Address	400 GILKEY RD ,	Approval Status	Approved
City, State, Zip	Burlington, WA 98233	Facility Type	Residential Care


On 07/12/2023 the Office of the State Fire Marshal conducted an inspection at your facility.

All violations noted during previous related inspection(s) have been corrected.

Owner or Owner's Representative

Signature

RICK A. GORDON / PLANT OPERATIONS DIRECTOR
Print Name and Title

Deputy State Fire Marshal Brandon G. Brown
16778 146 ST SE
Monroe WA 98272
(360) 791-7037


Signature

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name Creekside Continuing Care Community
Address 400 GILKEY RD ,
City, State, Zip Burlington, WA 98233

Provider Number 2316
Approval Status Disapproved
Facility Type Residential Care

On 06/12/2023 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

1 Extension Cords

Extension cords and flexible cords shall not be a substitute for permanent wiring and shall be listed and labeled in accordance with UL 817. Extension cords and flexible cords shall not be affixed to structures, extended through walls, ceilings or floors, or under doors or floor coverings, nor shall such cords be subject to environmental damage or physical impact. Extension cords shall be used only with portable appliances. Extension cords marked for indoor use shall not be used outdoors.

(IFC 604.5 2018)

The following violations were observed:

There was an extension cord utilized as permanent wiring in the Activities Director office.

2 Door Operation

Swinging fire doors shall close from the full-open position and latch automatically.

(IFC 705.2.4 2018)

The following violations were observed:

1. The fire rated door from the 2nd floor laundry near 210 to the corridor would not close and latch from a fully open position.
2. The cross corridor fire rated door near the Brauty Solan would not close and latch from a fully open position.
3. The double doors to the dining room had an inoperative door-closing coordinator, preventing the doors from closing and latching.

3 Inspection, Testing and Maintenance

The maintenance and testing schedules and procedures for fire alarm and fire detection systems shall be in accordance with Sections 907.8.1 through 907.8.5 and NFPA 72. Records of inspection, testing and maintenance shall be maintained.

(IFC 907.8 2018)

The following violations were observed:

The power breaker for fire alarm is missing locking device.

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Creekside Continuing Care Community	Provider Number	2316
Address	400 GILKEY RD ,	Approval Status	Disapproved
City, State, Zip	Burlington, WA 98233	Facility Type	Residential Care

On 06/12/2023 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

4 Power Test

Battery-powered emergency lighting equipment shall be tested annually by operating the equipment on battery power for not less than 90 minutes. (IFC 1031.10.2 2018)	The following violations were observed: Facility is unable to provide documentation for the annual 90 minute power test for the emergency lights.
---	--

Next inspection scheduled on or after: 07/12/2023

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Authorized Representative

Signature

Rick A. Gordon Plant Operations Director
Print Name and Title

Deputy State Fire Marshal Brandon G. Brown
16778 146 ST SE
Monroe WA 98272
(360) 791-7037

Signature

This document was prepared by Residential Care Services for the Locator website.