



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Fieldstone Memory Care	Provider Number	2646
Address	4120 ENGLEWOOD AVE ,	Approval Status	Approved
City, State, Zip	Yakima, WA 989082675	Facility Type	Residential Care

On 06/09/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

1 Relocatable power taps and current taps

Relocatable power taps and current taps. The construction and use of current taps and relocatable power taps shall be in accordance with NFPA 70 and this code.

(IFC 603.5, 2021)

The following violation was observed:

-In Room 26 there was an unfused power strip in use. (corrected)

2 Testing and Maintenance

Sprinkler systems shall be tested and maintained in accordance with Section 901.

(IFC 903.5 2021)

The following violation was observed:

-The facility failed to provide documentation of the annual forward flow testing on the fire sprinkler system. (corrected)

Next inspection scheduled on or after: 06/30/2026

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Authorized Representative

Signature

Print Name and Title

Deputy State Fire Marshal Andrea Ely
2715 RUDKIN RD
Union Gap WA
(509) 531-3384

Andrea Ely

Digitally signed by
Andrea Ely
Date: 2025.06.09
18:25:26 -07'00'

Signature



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Fieldstone Memory Care	Provider Number	2646
Address	4120 ENGLEWOOD AVE ,	Approval Status	Disapproved
City, State, Zip	Yakima, WA 989082675	Facility Type	Residential Care

On 05/06/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

1 Relocatable power taps and current taps

Relocatable power taps and current taps. The construction and use of current taps and relocatable power taps shall be in accordance with NFPA 70 and this code.

(IFC 603.5, 2021)

The following violation was observed:

-In Room 26 there was an unfused power strip in use.
(corrected)

2 Testing and Maintenance

Sprinkler systems shall be tested and maintained in accordance with Section 901.

(IFC 903.5 2021)

The following violation was observed:

-The facility failed to provide documentation of the annual forward flow testing on the fire sprinkler system.

Next inspection scheduled on or after: 06/05/2025

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Authorized Representative

Signature

Print Name and Title

Deputy State Fire Marshal Andrea Ely
2715 RUDKIN RD
Union Gap WA
(509) 531-3384

Andrea Ely

Signature

Digitally signed by
Andrea Ely
Date: 2025.05.06
12:55:35 -07'00'

Initials of Authorized Facility Representative: _____