



Post-Certification Revisit Report

Public reporting for this collection of information is estimated to average 10 minutes per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information including suggestions for reducing the burden, to CMS, Office of Financial Management, P.O. Box 26684, Baltimore, MD 21207; and to the Office of Management and Budget, Paperwork Reduction Project (0938-0390), Washington, D.C. 20503.

(Y1) Provider / Supplier / CLIA / Identification Number 53A002	(Y2) Multiple Construction A. Building B. Wing 01 - MAIN BUILDING 01	(Y3) Date of Revisit 8/23/2006
Name of Facility AMIE HOLT CARE CENTER		Street Address, City, State, Zip Code 497 W LOTT BUFFALO, WY 82834

This report is completed by a qualified State surveyor for the Medicare, Medicaid and/or Clinical Laboratory Improvement Amendments program, to show those deficiencies previously reported on the CMS-2567, Statement of Deficiencies and Plan of Correction that have been corrected and the date such corrective action was accomplished. Each deficiency should be fully identified using either the regulation or LSC provision number and the identification prefix code previously shown on the CMS-2567 (prefix codes shown to the left of each requirement on the survey report form).

(Y4) Item	(Y5) Date	(Y4) Item	(Y5) Date	(Y4) Item	(Y5) Date
ID Prefix _____ Reg. # NFPA 101 LSC K0014	Correction Completed 07/20/2006	ID Prefix _____ Reg. # NFPA 101 LSC K0018	Correction Completed 08/01/2006	ID Prefix _____ Reg. # NFPA 101 LSC K0025	Correction Completed 07/28/2006
ID Prefix _____ Reg. # NFPA 101 LSC K0029	Correction Completed 07/28/2006	ID Prefix _____ Reg. # NFPA 101 LSC K0038	Correction Completed 08/11/2006	ID Prefix _____ Reg. # NFPA 101 LSC K0052	Correction Completed 07/31/2006
ID Prefix _____ Reg. # NFPA 101 LSC K0056	Correction Completed 07/27/2006	ID Prefix _____ Reg. # NFPA 101 LSC K0064	Correction Completed 07/19/2006	ID Prefix _____ Reg. # NFPA 101 LSC K0075	Correction Completed 07/19/2006
ID Prefix _____ Reg. # NFPA 101 LSC K0147	Correction Completed 07/19/2006	ID Prefix _____ Reg. # _____ LSC _____	Correction Completed	ID Prefix _____ Reg. # _____ LSC _____	Correction Completed
ID Prefix _____ Reg. # _____ LSC _____	Correction Completed	ID Prefix _____ Reg. # _____ LSC _____	Correction Completed	ID Prefix _____ Reg. # _____ LSC _____	Correction Completed

Reviewed By _____ State Agency	Reviewed By 	Date: _____	Signature of Surveyor: 	Date: _____
Reviewed By _____ CMS RO	Reviewed By _____	Date: _____	Signature of Surveyor: 	Date: _____
Followup to Survey Completed on: 6/27/2006		Check for any Uncorrected Deficiencies. Was a Summary of Uncorrected Deficiencies (CMS-2567) Sent to the Facility? YES NO		