

Healthcare Licensing and Surveys

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: ALF020	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING: _____		(X3) DATE SURVEY COMPLETED R 01/30/2020
NAME OF PROVIDER OR SUPPLIER LEGACY HOMES ASSISTED LIVING			STREET ADDRESS, CITY, STATE, ZIP CODE 2391 MUDDY STRING RD 117 THAYNE, WY 83127		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE	
{S 000}	General Comments A Life Safety Code revisit survey was conducted by Healthcare Licensing and Surveys on 1/30/2020 for all deficiencies cited on 12/18/2019. All previous deficiencies have been corrected and the facility is now back in compliance.	{S 000}			

Wyoming Dept of Health, Aging Division, Healthcare Licensing and Surveys
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE