

Agency for Health Care Administration

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: AL11965233	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING: _____	(X3) DATE SURVEY COMPLETED R
NAME OF PROVIDER OR SUPPLIER CASTLE COURT ALF, INC.		STREET ADDRESS, CITY, STATE, ZIP CODE 9709 NORTH NEBRASKA AVENUE TAMPA, FL 33612		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{A 000}	Initial Comments Assisted Living Facility A revisit survey was conducted on 2013. Castle Court ALF, Inc. had an uncorrected deficiency found at the time of the visit.	{A 000}		
{A 152}	58A-5.023(3) FAC Physical Plant - Safe Living Environ/Other (3) OTHER REQUIREMENTS. (a) All facilities must: 1. Provide a safe living environment pursuant to Section 429.28(1)(a), F.S.; and 2. Must be maintained free of hazards; and 3. Must ensure that all existing architectural, mechanical, electrical and structural systems and appurtenances are maintained in good working order. (b) Pursuant to Section 429.27, F.S., residents shall be given the option of using their own belongings as space permits. When the facility supplies the furnishings, each resident sleeping area must have at least the following furnishings: 1. A clean, comfortable bed with a mattress no less than 36 inches wide and 72 inches long, with the top surface of the mattress a comfortable height to ensure easy access by the resident; 2. A closet or wardrobe space for hanging clothes; 3. A dresser, chest or other furniture designed for storage of personal effects; 4. A table, bedside lamp or floor lamp, and waste basket; and 5. A comfortable chair, if requested. (c) The facility must maintain master or duplicate keys to resident to be used in the event of an emergency.	{A 152}		

AHCA Form 3020-0001

TITLE

(X6) DATE

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

STATE FORM

0000

3T5C12

If continuation sheet 1 of 2

Agency for Health Care Administration

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: AL11965233	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING: _____	(X3) DATE SURVEY COMPLETED R
NAME OF PROVIDER OR SUPPLIER CASTLE COURT ALF, INC.		STREET ADDRESS, CITY, STATE, ZIP CODE 9709 NORTH NEBRASKA AVENUE TAMPA, FL 33612		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{A 152}	Continued From page 1 (d) Residents who use portable bedside commodes must be provided with privacy during use. (e) Facilities must make available linens and personal laundry services for residents who require such services. Linens provided by a facility shall be free of tears, stains and not be This Statute or Rule is not met as evidenced by: Based on observations and interview the facility failed to ensure the wall and ceiling in one in good repair for 1 of 5 toured observed. Findings include: On at approximately 9:57 a.m. Three large holes were observed in on the wall next to Resident #2 's bed. One ceiling tile in this observed to not properly fitted to the ceiling, leaving a gap in the ceiling of this Resident #2's On at approximately 9:59 a.m. The owner was interviewed. He acknowledged the findings and denied knowing how long the ceiling or the wall in this been in this condition. The owner Stated the holes on Resident #2 's were made by Resident #2 punching the wall. The owner stated the hole were previously repaired. The owner denied having documentation of previous repairs. Class III	{A 152}		

State Form: Revisit Report

(Y1) Provider / Supplier / CLIA / Identification Number AL11965233	(Y2) Multiple Construction A. Building B. Wing	(Y3) Date of Revisit 5/9/2013
Name of Facility CASTLE COURT ALF, INC.		Street Address, City, State, Zip Code 9709 NORTH NEBRASKA AVENUE TAMPA, FL 33612

This report is completed by a State surveyor to show those deficiencies previously reported that have been corrected and the date such corrective action was accomplished. Each deficiency should be fully identified using either the regulation or LSC provision number and the identification prefix code previously shown on the State Survey Report (prefix codes shown to the left of each requirement on the survey report form).

(Y4) Item	(Y5) Date	(Y4) Item	(Y5) Date	(Y4) Item	(Y5) Date
ID Prefix <u>A0008</u> Reg. # <u>58A-5.0181(2) FAC</u> LSC _____	Correction Completed	ID Prefix <u>A0052</u> Reg. # <u>58A-5.0185(3) FAC</u> LSC _____	Correction Completed	ID Prefix <u>A0055</u> Reg. # <u>58A-5.0185(6) FAC</u> LSC _____	Correction Completed
ID Prefix <u>A0078</u> Reg. # <u>58A-5.019(2) FAC</u> LSC _____	Correction Completed	ID Prefix <u>A0093</u> Reg. # <u>58A-5.020(2) FAC</u> LSC _____	Correction Completed	ID Prefix <u>AZ815</u> Reg. # <u>408.809, 435.02(2), 435.06</u> LSC _____	Correction Completed
ID Prefix _____ Reg. # _____ LSC _____	Correction Completed	ID Prefix _____ Reg. # _____ LSC _____	Correction Completed	ID Prefix _____ Reg. # _____ LSC _____	Correction Completed
ID Prefix _____ Reg. # _____ LSC _____	Correction Completed	ID Prefix _____ Reg. # _____ LSC _____	Correction Completed	ID Prefix _____ Reg. # _____ LSC _____	Correction Completed
ID Prefix _____ Reg. # _____ LSC _____	Correction Completed	ID Prefix _____ Reg. # _____ LSC _____	Correction Completed	ID Prefix _____ Reg. # _____ LSC _____	Correction Completed

Reviewed By 	Date: <u>5/24/13</u>	Signature of Surveyor: _____	Date: _____
Reviewed By _____	Date: _____	Signature of Surveyor: _____	Date: _____

Followup to Survey Completed on: _____

Check for any Uncorrected Deficiencies. Was a Summary of Uncorrected Deficiencies (CMS-2567) Sent to the Facility?

YES NO



RICK SCOTT
GOVERNOR

ELIZABETH DUDEK
SECRETARY

2013

Administrator
Castle Court ALF, Inc.
9709 North Nebraska Avenue
Tampa, FL 33612


Dear Administrator:

This letter reports the findings of a state licensure survey revisit that was conducted on 2013, by a representative of this office.

Attached is the provider's copy of the State (3020) Form, which indicates the uncorrected deficiency that was identified on the day of the visit. Section 408.811(4), Florida Statutes, requires that you correct this deficiency within thirty days of the date of this letter unless the Agency has approved another timeframe. Staff from this office will conduct a review to verify that the necessary corrections are in place to correct the deficiency identified on your survey.

The Quality Assurance Questionnaire has long been employed to obtain your feedback following survey activity. This form has been placed on the Agency's website at <http://ahca.myflorida.com/Publications/Forms.shtml> as a first step in providing a web-based interactive consumer satisfaction survey system. You may access the questionnaire through the link under **Health Facilities and Providers** on this page. Your feedback is encouraged and valued, as our goal is to ensure the professional and consistent application of the survey process.

Thank you for the assistance provided to the surveyor. Should you have any questions please call **Paul Brown**, HFES, at 727-552-2000.

Sincerely,

FOV Patricia Reid Kaufman
Field Office Manager

PRC/kpr

Enclosure: State Form 3020

Headquarters
2727 Mahan Drive
Tallahassee, FL 32308
<http://ahca.myflorida.com>



St. Petersburg Field Office
525 Mirror Lake Drive North, Suite 410 A
St. Petersburg, FL 33701
Phone (727) 552-2000; Fax (727) 552-1161