

MSDH - Health Facilities Licensure and Certification

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 61AI	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 - BUILDING 78 B. WING _____	(X3) DATE SURVEY COMPLETED 10/10/2023
NAME OF PROVIDER OR SUPPLIER JNH-JAQUITH INN		STREET ADDRESS, CITY, STATE, ZIP CODE 3550 HIGHWAY 468 WEST WHITFIELD, MS 39193		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
M1245	45.41.1 Date of Construction & Life Safety... Date of Construction and Life Safety Code Compliance. 1. Buildings constructed after the effective date of these regulations shall comply with the edition of the Life Safety Code (NFPA 101) effective on the date of construction. 2. Buildings constructed prior to the effective date of these regulations shall comply with Chapter 13 of the Life Safety Code (NFPA 101), 1985 edition. This Statute is not met as evidenced by: Based on the review of documentation, the facility failed to properly document records of testing the generator annually as directed by NFPA 99 sections 6.4.4.1.1.3 and 6.4.4.2. This deficient practice had potential of affecting the entire facility on the day of facility survey. Findings include: On 10/10/23 at 1:00 PM, the facility could not produce documentation showing the current 2023 annual testing and service of the generator. The facility's last annual test of the generator was documented and performed 4/5/22. The finding was acknowledged by the Administrator and Maintenance Supervisor during the exit interview on 10/10/23.	M1245	The facility could not produce documentation showing the current 2023 annual test and service of the generator. On 10/31/2023, The facility acquired a vendor to inspect and service the generator and a purchase order was issued. 37 residents have the potential to be affected by the deficient practice. On 10/31/2023 the Jaquith Inn Quality Assurance Performance Improvement (QAPI) Coordinator in-serviced the Coordinator Unit Operations (CUO) and the Maintenance Supervisor on maintaining documentation for generator service check. Beginning 11/2/2023, the vendor will conduct an annual generator inspection. Upon completion of inspection, the vendor will submit inspection report to the facility's maintenance department. The facility's maintenance dept. will forward a copy of the inspection report to the QAPI Coord. The QAPI Coord. will notify the Quality Assurance Performance Improvement (QAPI) Committee Six (6) months and	11/10/23

Mississippi State Department of Health

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Electronically Signed

11/01/23

MSDH - Health Facilities Licensure and Certification

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 61AI	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 - BUILDING 78 B. WING _____	(X3) DATE SURVEY COMPLETED 10/10/2023
NAME OF PROVIDER OR SUPPLIER JNH-JAQUITH INN		STREET ADDRESS, CITY, STATE, ZIP CODE 3550 HIGHWAY 468 WEST WHITFIELD, MS 39193		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
M1245	Continued From page 1	M1245	then three (3) months prior to inspection expiration date. Beginning 11/1/2023 the NHA will report all findings to the QAPI Committee every six months for action until consistent substantial compliance has been achieved as determined by the committee. Should systemic changes not be effective, the QAPI Committee will investigate and determined if further action(s) need to be implemented. The actions from the QAPI meeting will be reported to Jaquith Nursing Home Executive Committee.	