

MSDH - Health Facilities Licensure and Certification

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 54BM	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 - MAIN BUILDING 01 B. WING _____	(X3) DATE SURVEY COMPLETED 07/28/2022
NAME OF PROVIDER OR SUPPLIER DIVERSICARE OF BATESVILLE		STREET ADDRESS, CITY, STATE, ZIP CODE 154 WOODLAND ROAD BATESVILLE, MS 38606		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
M1245	45.41.1 Date of Construction & Life Safety... Date of Construction and Life Safety Code Compliance. 1. Buildings constructed after the effective date of these regulations shall comply with the edition of the Life Safety Code (NFPA 101) effective on the date of construction. 2. Buildings constructed prior to the effective date of these regulations shall comply with Chapter 13 of the Life Safety Code (NFPA 101), 1985 edition. This Statute is not met as evidenced by: Based on record review and interviews, the facility failed to properly perform fire drills as per NFPA 101 section 19.7.1.2. The deficient practice affected all smoke compartments and residents in facility on the day of survey. Findings Include: On 7/26/22 at 11:20 AM, the facility could not provide complete and proper documentation of fire drills. The following fire drill documentation information was not provided during the survey: No times and narrative of what was done of the fire drills for the 1st and 2nd shifts in the 2nd quarter of 2022 No employee/ staff signature page of the 2nd shift for the 3rd and 4th quarters of 2021	M1245	1.Maintenance Supervisor was in-service by Administrator on July 27, 2022 that fire drills should be held at varying times and logs maintained. 2.All Residents could be affected. 3.Monthly log to be kept by Maintenance Supervisor with varying times noted. 4.Maintenance Supervisor and Administrator will review fire drill reports and monitor fire drills monthly for two quarters. Maintenance Supervisor and Administrator will ensure fire drill reports are maintained and always available for review according to code NFPA 101 requirements to have at least one fire drill for every shift every three months. Finding will brought to Quality Assurance for discussion and resolution.	8/31/22

Mississippi State Department of Health
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Electronically Signed

08/12/22

MSDH - Health Facilities Licensure and Certification

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 54BM	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 - MAIN BUILDING 01 B. WING _____	(X3) DATE SURVEY COMPLETED 07/28/2022
NAME OF PROVIDER OR SUPPLIER DIVERSICARE OF BATESVILLE		STREET ADDRESS, CITY, STATE, ZIP CODE 154 WOODLAND ROAD BATESVILLE, MS 38606		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
M1245	Continued From page 1 No fire drill documentation for the 1st shift fire in the first quarter of 2022 No fire drill documentation for the 1st shift fire in the 4th quarter of 2021. The finding was acknowledged by the Administrator verified this observation during the exit interview on 7/26/22.	M1245		