

MSDH - Health Facilities Licensure and Certification

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 30CD	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 - MAIN BUILDING 01 B. WING _____	(X3) DATE SURVEY COMPLETED 04/12/2023
NAME OF PROVIDER OR SUPPLIER DIVERSICARE OF MOSS POINT		STREET ADDRESS, CITY, STATE, ZIP CODE 3401 MAIN STREET MOSS POINT, MS 39563		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
M1245	45.41.1 Date of Construction & Life Safety... Date of Construction and Life Safety Code Compliance. 1. Buildings constructed after the effective date of these regulations shall comply with the edition of the Life Safety Code (NFPA 101) effective on the date of construction. 2. Buildings constructed prior to the effective date of these regulations shall comply with Chapter 13 of the Life Safety Code (NFPA 101), 1985 edition. This Statute is not met as evidenced by: Based on the review of documentation, the facility failed to properly document records of testing the generator annually as directed by NFPA 110 section 8.4.2, NFPA 99 sections 6.4.4.1.1.3 and 6.4.4.2. This deficient practice had potential of affecting the entire facility on the day of facility survey. Findings include: On 4/12/23 at 11:30 AM, the facility could not produce the documentation for the annual inspection of the generator with the calendar year 2022. The finding was acknowledged by the Administrator and Maintenance Supervisor verified this observation during the exit interview on 4/12/23.	M1245	1) The generator was previously inspected on 9/29/2022, meeting the annual requirement; the report was placed in the facility Life Safety Book on 4/26/2023. 2) All residents within the facility have the potential to be affected by this issue. 3) Maintenance staff were in-serviced on 4/27/2023 by Administrator regarding the requirement to update and maintain documentation regarding the annual inspection for the facility generator as required. 4) Generator inspection documentation and upkeep of the Life Safety book will be brought to QA by Maintenance Supervisor, 1x monthly x3 months.	5/15/23

Mississippi State Department of Health
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Electronically Signed

05/01/23