

PRINTED: 09/22/2015
FORM APPROVED

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL035024	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED R 09/08/2015
NAME OF PROVIDER OR SUPPLIER FRANKLIN MANOR ASSISTED LIVING CENTER		STREET ADDRESS, CITY, STATE, ZIP CODE 100 SUNSET DR YOUNGSVILLE, NC 27596		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
(C 000)	Initial Comments This report is of a Followup Survey done by Bob Getchell on September 8, 2015. The followup survey revealed that all deficiencies have not been corrected, therefore a new plan of correction is required.	(C 000)	CONSTRUCTION SECTION SEP 29 2015 RECEIVED	
(C 189)	Building Equipment Maintained Safe, Operating SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 3. Based on observation, the Building was not maintained in a safe and operating condition because the commercial kitchen hood's fire extinguishing system lacked the inspections, maintenance and documentation required to ensure a properly working system. Followup Findings on 9-8-15 include: b. Since the semi-annual maintenance of the commercial kitchen hood's fire extinguishing system in March 2015, there has been no recording on the tag of the monthly inspections.	(C 189)		

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE *Humbly Richardson* DATE *9.29.15*

Interim Executive Director

Fire Alarm and Life Safety System Inspection Certificate

For

Franklin Manor
100 Sunset Dr.
Youngsville, NC 27596

Tested to NFPA 72 Standards

This inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date
Sep 9, 2015

Building: Franklin Manor
Contact: Kimberly Richardson
Title: Administrator

Company: Modern Systems Inc
Contact: Darin Matherly
Title: Technician

Executive Summary

Generated by: BuildingReports.com

Building Information		
Building: Franklin Manor	Contact: Kimberly Richardson	
Address: 100 Sunset Dr.	Phone: (919)562-5550	
Address:	Fax:	
City/State/Zip: Youngsville, NC 27596	Mobile:	
Country: United States of America	Email: Kimberly.Richardson@SaberHealth.com	
Inspection Performed By		
Company: Modern Systems Inc	Inspector: Darin Matherly	
Address: 1111 Old Stage Road	Phone: 336.463.5205	
Address:	Fax:	
City/State/Zip: Yadkinville, NC 27055	Mobile:	
Country: United States of America	Email: dmatherly@modernsys.biz	
System Control Unit		
Manufacturer: Fire-Lite	Inspection Date: 09/09/2015	IDC Style:
Model Number: MS9600UDLS	Install Date: 05/06/2013	SLC Style: 4
Software Version: 4.5 B3	Version Date: 10/13/2011	NAC Style: Y
Location: Outside Riser Room / Electrical	Current Protection: Breaker	
Monitoring		
Company:	Phone:	Account #:
Central Station Signal Verification		
Type: Digital Communicator	Mfg: Fire-Lite	Model #:
Test Time/Date: 9/9/15 11:13:17 AM	Restore Time	MS9600UDLS

Inspection Summary								
Category	Total Items		Serviced		Passed		Failed/Other	
	Qty	%	Qty	%	Qty	%	Qty	%
Auxiliary	3	2.61%	3	100.00%	3	100.00%	0	0%
Sound Test	1	0.87%	1	100.00%	1	100.00%	0	0%
Initiating	99	86.09%	99	100.00%	99	100.00%	0	0%
Control	12	10.43%	12	100.00%	8	66.67%	4	33.33%
Totals	115	100%	115	100.00%	111	96.52%	4	3.48%

Certification	
Company: Modern Systems Inc	Building: Franklin Manor
Inspector: Darin Matherly	Contact: Kimberly Richardson
Signed:	Signed:
Darin Matherly	
Certification Type	Number

Discrepancy Report

Generated by: BuildingReports.com

Building: Franklin Manor		Control Panel: 1 - Fire-Lite MS9600UDLS		
<i>The Discrepancy Report consolidates each discrepancy listed within the various Testing sections of your Inspection. Discrepancies are listed by Category, and grouped by device type. The description of the problem is provided and where appropriate, code references are listed for your convenience. Any item that was inspected that is listed on the Consumer Product Safety Commission's website and is subject to a recall by the manufacturer is included.</i>				
Device Type	Manufacturer	ModelNumber	Date	Qty
Items listed for Recall by Manufacturer				
No recalled items found during this inspection.				
ScanID	Location	Problem	Address	Reference
Control				
Battery				
29885848	Outside Riser Room / Electrical In FACP	Failed Test	1	NFPA72 Table 14.4.2.2 (5)(b)
29885849	Outside Riser Room / Electrical In FACP	Failed Test	1	NFPA72 Table 14.4.2.2 (5)(b)
29885855	Outside Riser Room / Electrical In FCPS	Failed Test	1	NFPA72 Table 14.4.2.2 (5)(b)
29885856	Outside Riser Room / Electrical In FCPS	Failed Test	1	NFPA72 Table 14.4.2.2 (5)(b)
Code References				
NFPA72 Table 14.4.2.2 (5)(b)	Batteries shall be replaced in accordance with the recommendations of the alarm equipment manufacturer or when the recharged battery voltage or current falls below the manufacturer's recommendations.			

Proposed Solutions Report

Generated by: BuildingReports.com

Building: Franklin Manor

Control Panel: 1 - Fire-Lite
MS9600UDLS

The Proposed Solution Report provides a solution for each discrepancy listed on the Discrepancy Report. Provide a check mark where indicated to approve repairs listed within the report. Items listed as T/M are available for repair on a Time and Materials basis.

ScanID	Location	Solution	Model #	Cost	Fix	Fixed Date
Control						
Battery						
29885848	Outside Riser Room / Electrical In FACP	Replace	PS-12260 NB	T/M	☒	09/18/15
29885849	Outside Riser Room / Electrical In FACP	Replace	PS-12260 NB	T/M	☒	09/18/15
29885855	Outside Riser Room / Electrical In FCPS	Replace	NP7-12	T/M	☒	09/18/15
29885856	Outside Riser Room / Electrical In FCPS	Replace	NP7-12	T/M	☒	09/18/15

Inspection & Testing

Generated by: BuildingReports.com

Building: Franklin Manor		Control Panel: 1 - Fire-Lite MS9600UDLS		
The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.				
Device Type	Location	Service	Time	Date
Passed				
Auxiliary				
Fan Shutdown	All	Tested	11:13:16 AM	09/09/2015
Locking Device	All	Tested	11:13:16 AM	09/09/2015
Releasing Device	All	Tested	11:13:15 AM	09/09/2015
Control				
Annunciator	Reception Desk	Tested	9:25:04 AM	09/09/2015
Annunciator	Exit By Room 120	Tested	10:15:43 AM	09/09/2015
Annunciator	Left Nurses Station	Tested	9:32:38 AM	09/09/2015
Annunciator	Right Nurses Station	Tested	10:11:52 AM	09/09/2015
Communicator	Outside Riser Room / Electrical	Tested	11:13:17 AM	09/09/2015
Control Panel	Outside Riser Room / Electrical	Tested	9:18:12 AM	09/09/2015
Disconnect	Exit By Room 120	Tested	11:13:40 AM	09/09/2015
Power Supply	Outside Riser Room / Electrical Beside FACP	Tested	11:11:41 AM	09/09/2015
Initiating				
Heat Detector	Kitchen	Tested	10:53:25 AM	09/09/2015
Heat Detector	Kitchen	Tested	10:53:56 AM	09/09/2015
Heat Detector	Outside Riser Room / Electrical Above FACP	Tested	9:20:14 AM	09/09/2015
Pull Station	Kitchen	Tested	10:11:07 AM	09/09/2015
Pull Station	Main Lobby	Tested	9:26:47 AM	09/09/2015
Pull Station	Exit By Room 100	Tested	10:03:18 AM	09/09/2015
Pull Station	Exit By Room 120	Tested	10:40:33 AM	09/09/2015
Pull Station	Exit By Room 121	Tested	9:37:59 AM	09/09/2015
Pull Station	Exit By Room 139	Tested	10:20:52 AM	09/09/2015
Pull Station	Left Living Room Exit	Tested	9:34:51 AM	09/09/2015
Pull Station	Left Nurse Station	Tested	9:32:50 AM	09/09/2015
Smoke Detector	Administrator Office	Tested	10:34:20 AM	09/09/2015
Smoke Detector	Business Office	Tested	9:25:41 AM	09/09/2015
Smoke Detector	Clean Linen Right Side	Tested	10:01:51 AM	09/09/2015
Smoke Detector	Discovery Room	Tested	9:27:41 AM	09/09/2015
Smoke Detector	Laundry Room	Tested	10:48:12 AM	09/09/2015
Smoke Detector	Lobby At Mens Room	Tested	9:24:29 AM	09/09/2015
Smoke Detector	Main Lobby	Tested	9:26:13 AM	09/09/2015
Smoke Detector	Reception Desk	Tested	9:25:02 AM	09/09/2015
Smoke Detector	100 Employee Lounge	Tested	10:43:20 AM	09/09/2015
Smoke Detector	Activities Director Office	Tested	9:30:42 AM	09/09/2015
Smoke Detector	Dining Room By Activities Director	Tested	9:30:13 AM	09/09/2015
Smoke Detector	Dining Room By Kitchen	Tested	9:29:45 AM	09/09/2015

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	Dining Room By Nurses Station	Tested	9:31:31 AM	09/09/2015
Smoke Detector	Dining Room By Piano	Tested	9:28:46 AM	09/09/2015
Smoke Detector	Dining Room By Storage	Tested	9:29:16 AM	09/09/2015
Smoke Detector	Exit By Room 120	Tested	10:39:48 AM	09/09/2015
Smoke Detector	Hall At Employee Lounge	Tested	10:15:10 AM	09/09/2015
Smoke Detector	Hall By Care Base	Tested	10:13:17 AM	09/09/2015
Smoke Detector	Hall By Left Nurses Station	Tested	9:31:57 AM	09/09/2015
Smoke Detector	Hall By Room 105	Tested	9:35:36 AM	09/09/2015
Smoke Detector	Hall By Room 108	Tested	9:36:01 AM	09/09/2015
Smoke Detector	Hall By Room 111	Tested	9:36:19 AM	09/09/2015
Smoke Detector	Hall By Room 112	Tested	9:36:47 AM	09/09/2015
Smoke Detector	Hall By Room 116	Tested	9:37:13 AM	09/09/2015
Smoke Detector	Hall By Room 121	Tested	9:37:32 AM	09/09/2015
Smoke Detector	Hall By Room 123	Tested	10:18:25 AM	09/09/2015
Smoke Detector	Hall By Room 124	Tested	10:14:08 AM	09/09/2015
Smoke Detector	Hall By Room 126	Tested	10:13:46 AM	09/09/2015
Smoke Detector	Hall By Room 128	Tested	10:19:08 AM	09/09/2015
Smoke Detector	Hall By Room 130	Tested	10:19:30 AM	09/09/2015
Smoke Detector	Hall By Room 132	Tested	9:28:23 AM	09/09/2015
Smoke Detector	Hall By Room 132	Tested	10:19:53 AM	09/09/2015
Smoke Detector	Hall By Room 136	Tested	10:20:15 AM	09/09/2015
Smoke Detector	Hall By Room 139	Tested	10:20:34 AM	09/09/2015
Smoke Detector	Hall By Left Nurses Station	Tested	9:34:00 AM	09/09/2015
Smoke Detector	Hall At Room 102	Tested	10:02:52 AM	09/09/2015
Smoke Detector	Hall At Room 104	Tested	10:00:19 AM	09/09/2015
Smoke Detector	Hall At Discovery Room	Tested	9:27:09 AM	09/09/2015
Smoke Detector	Hall At Laundry Room	Tested	10:01:31 AM	09/09/2015
Smoke Detector	Hall At Special Care Coordinator	Tested	9:59:54 AM	09/09/2015
Smoke Detector	Left Living Room	Tested	9:34:24 AM	09/09/2015
Smoke Detector	Left Living Room Near Exit	Tested	9:35:08 AM	09/09/2015
Smoke Detector	Left Med Room	Tested	9:33:39 AM	09/09/2015
Smoke Detector	Left Nurse Station	Tested	10:37:30 AM	09/09/2015
Smoke Detector	Living Room	Tested	10:33:19 AM	09/09/2015
Smoke Detector	Living Room By TV	Tested	10:32:40 AM	09/09/2015
Smoke Detector	Personal Care Beauty Salon	Tested	10:14:34 AM	09/09/2015
Smoke Detector	Right Med Room	Tested	10:12:40 AM	09/09/2015
Smoke Detector	Right Nurses Station	Tested	10:12:12 AM	09/09/2015
Smoke Detector	Room 100	Tested	10:47:26 AM	09/09/2015
Smoke Detector	Room 102	Tested	10:04:26 AM	09/09/2015
Smoke Detector	Room 104	Tested	10:05:15 AM	09/09/2015
Smoke Detector	Room 105	Tested	9:50:54 AM	09/09/2015
Smoke Detector	Room 106	Tested	10:07:55 AM	09/09/2015
Smoke Detector	Room 107	Tested	9:49:12 AM	09/09/2015
Smoke Detector	Room 108	Tested	9:47:44 AM	09/09/2015
Smoke Detector	Room 109	Tested	9:48:27 AM	09/09/2015
Smoke Detector	Room 110	Tested	10:36:07 AM	09/09/2015
Smoke Detector	Room 111	Tested	9:46:01 AM	09/09/2015
Smoke Detector	Room 112	Tested	10:49:29 AM	09/09/2015
Smoke Detector	Room 113	Tested	9:44:52 AM	09/09/2015
Smoke Detector	Room 114	Tested	9:42:51 AM	09/09/2015

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	Room 115	Tested	10:50:16 AM	09/09/2015
Smoke Detector	Room 116	Tested	9:42:18 AM	09/09/2015
Smoke Detector	Room 117	Tested	9:43:51 AM	09/09/2015
Smoke Detector	Room 118	Tested	10:51:01 AM	09/09/2015
Smoke Detector	Room 119	Tested	9:40:09 AM	09/09/2015
Smoke Detector	Room 120	Tested	10:16:16 AM	09/09/2015
Smoke Detector	Room 121	Tested	9:38:18 AM	09/09/2015
Smoke Detector	Room 122	Tested	11:05:30 AM	09/09/2015
Smoke Detector	Room 123	Tested	10:31:58 AM	09/09/2015
Smoke Detector	Room 124	Tested	10:17:07 AM	09/09/2015
Smoke Detector	Room 125	Tested	10:31:10 AM	09/09/2015
Smoke Detector	Room 126	Tested	10:17:48 AM	09/09/2015
Smoke Detector	Room 127	Tested	10:30:12 AM	09/09/2015
Smoke Detector	Room 128	Tested	10:29:38 AM	09/09/2015
Smoke Detector	Room 129	Tested	10:27:21 AM	09/09/2015
Smoke Detector	Room 130	Tested	10:28:38 AM	09/09/2015
Smoke Detector	Room 131	Tested	10:26:32 AM	09/09/2015
Smoke Detector	Room 132	Tested	10:27:58 AM	09/09/2015
Smoke Detector	Room 133	Tested	10:25:39 AM	09/09/2015
Smoke Detector	Room 134	Tested	10:24:04 AM	09/09/2015
Smoke Detector	Room 135	Tested	10:24:44 AM	09/09/2015
Smoke Detector	Room 136	Tested	10:23:33 AM	09/09/2015
Smoke Detector	Room 137	Tested	10:21:59 AM	09/09/2015
Smoke Detector	Room 138	Tested	10:22:52 AM	09/09/2015
Smoke Detector	Room 139	Tested	10:21:21 AM	09/09/2015
Smoke Detector	Special Care Coordinator	Tested	10:00:57 AM	09/09/2015
Device Type	Location	Service	Time	Date
<i>Failed/Other</i>				
Control				
Battery	Outside Riser Room / Electrical In FACP	Tested	11:12:55 AM	09/09/2015
Battery	Outside Riser Room / Electrical In FACP	Tested	11:13:12 AM	09/09/2015
Battery	Outside Riser Room / Electrical In FCPS	Tested	11:12:04 AM	09/09/2015
Battery	Outside Riser Room / Electrical In FCPS	Tested	11:12:25 AM	09/09/2015

Service Summary

Generated by: BuildingReports.com

Building: Franklin Manor

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
<i>Failed/Other</i>		
Battery	Tested	4
Total		4
<i>Passed</i>		
Annunciator	Tested	4
Communicator	Tested	1
Control Panel	Tested	1
Disconnect	Tested	1
Fan Shutdown	Tested	1
Heat Detector	Tested	3
Locking Device	Tested	1
Power Supply	Tested	1
Pull Station	Tested	8
Releasing Device	Tested	1
Smoke Detector	Tested	88
Total		110

Auxiliary Functions Testing

Generated by: BuildingReports.com

Building: Franklin Manor		Control Panel: 1 - Fire-Lite MS9600UDLS		
The Auxiliary Functions Testing section lists each of the ancillary items, systems, and emergency equipment that are controlled by the system control unit. Items are grouped by Passed or Failed/Other. The items are listed by device type, and a check box is provided to indicate if the test conducted was simulated.				
Type	Location	Comment	ScanID	Simulated
Passed				
Fan Shutdown				
Return	All	Passed	29885853	☐
Locking Device				
Magnetic Lock	All	Passed	29885851	☐
Releasing Device				
Door Holder	All	Passed	29885852	☐

Sound and Visual Testing

Generated by: BuildingReports.com

Building: Franklin Manor						
The Sound and Visual Testing section lists various points throughout your building where audible and visual alarm notification devices were tested. Any bar-coded audible and visual devices will appear in the Inspection and Testing section of this report. Items in this section are grouped by Passed or Failed/Other. Where specific decibel readings were recorded, they will appear under the ambient and alarm columns. The Voice column indicates whether the Sound Test Point passed the Voice Intelligibility requirements. The STI or Sound Transmission Index is shown if recorded.						
☐ Location	Comment	Ambient dB	Alarm dB	Intelligibility		Sound
				Voice	STI	Test
Passed						
Sound Test Points						
All	Passed			☐		0001

Smoke Management Testing

Generated by: BuildingReports.com

Building: Franklin Manor		Control Panel: 1 - Fire-Lite MS9600UDLS		
<i>The Smoke Management Testing section details the test and inspection of device items that are involved in controlling the spread of smoke in a building. Items are grouped by Passed or Failed/Other.</i>				
☐ Location	Description	 Comment	ScanID	Simulated
<i>Passed</i>				
Fan Shutdown				
All	Return	Passed	29885853	☐
Releasing Device				
All	Door Holder	Passed	29885852	☐

Battery & Power Supply Testing

Generated by: BuildingReports.com

Building: Franklin Manor			Control Panel: 1 - Fire-Lite MS9600UDLS			
<i>The Control & Power Testing section details the readings and measurements of batteries and power supplies used to provide power to the fire alarm and life safety systems. Items are grouped by Passed or Failed/Other.</i>						
Type	Location	Comment	Amps	Volts	Pre Test	Post Test
Passed						
Power Supply						
	Outside Riser Room / Electrical Beside FACP	Passed	20	120		
Failed/Other						
Battery						
Sealed Lead Acid	Outside Riser Room / Electrical In FACP	Failed Test	26	12	13.3V	14A
Sealed Lead Acid	Outside Riser Room / Electrical In FACP	Failed Test	26	12	13.3V	12A
Sealed Lead Acid	Outside Riser Room / Electrical In FCPS	Failed Test	7	12	13.0V	2.1A
Sealed Lead Acid	Outside Riser Room / Electrical In FCPS	Failed Test	7	12	12.7V	3.3A

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: Franklin Manor		Control Panel: 1 - Fire-Lite MS9600UDLS		
The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.				
Device or Item	Category	% of Inventory		Quantity
Control Panel	Control	0.87%		1
Heat Detector	Initiating	2.61%		3
Smoke Detector	Initiating	76.52%		88
Annunciator	Control	3.48%		4
Pull Station	Initiating	6.96%		8
Power Supply	Control	0.87%		1
Battery	Control	3.48%		4
Releasing Device	Auxiliary	0.87%		1
Fan Shutdown	Auxiliary	0.87%		1
Locking Device	Auxiliary	0.87%		1
Communicator	Control	0.87%		1
Disconnect	Control	0.87%		1
Type	Qty	Model #	Description	Install Date
In Service - 2 Years to 3 Years				
Disconnect	1		Breaker 29 Panel EMA	05/06/2013
Fan Shutdown	1		Return	05/06/2013
Locking Device	1		Magnetic Lock	05/06/2013
Releasing Device	1		Door Holder	05/06/2013
Fire-Lite				
Annunciator	4	LCD-80	LCD Display	05/06/2013
Communicator	1	MS9600UDLS	Digital Communicator	05/06/2013
Control Panel	1	MS9600UDLS		05/06/2013
Heat Detector	3	H355	Fixed Temperature	05/06/2013
Power Supply	1	FCPS-24FS8		05/06/2013
Pull Station	8	BG-12LX	Dual Action	05/06/2013
Smoke Detector	1		Photoelectric	05/06/2013
Smoke Detector	87	SD355	Photoelectric	05/06/2013
Power-Sonic				
Battery	2	PS-12260 N8	Sealed Lead Acid	05/06/2013
YUASA				
Battery	2	NP7-12	Sealed Lead Acid	05/06/2013

Zone Address Report

Generated by: BuildingReports.com

Building: Franklin Manor

Control Panel: 1 - Fire-Lite
MS9600UDLS

The Zone Address Report lists all of the devices and items that have an individual address, or are grouped together under a common zone. The device type, location, and description are included for your reference.

Address	Device Type	Location	Type	ScanID
1D001	Smoke Detector	Left Nurse Station	Photoelectric	29885969
1D002	Smoke Detector	Hall By Left Nurses Station	Photoelectric	29885967
1D003	Smoke Detector	Left Living Room	Photoelectric	29885974
1D004	Smoke Detector	Dining Room By Nurses Station	Photoelectric	29885966
1D005	Smoke Detector	Hall By Left Nurses Station	Photoelectric	29885972
1D006	Smoke Detector	Lobby At Mens Room	Photoelectric	29885877
1D007	Smoke Detector	Main Lobby	Photoelectric	29885883
1D008	Smoke Detector	Hall At Discovery Room	Photoelectric	29885885
1D009	Smoke Detector	Hall By Room 132	Photoelectric	29885938
1D010	Smoke Detector	Dining Room By Plano	Photoelectric	29885962
1D011	Smoke Detector	Hall By Care Base	Photoelectric	29885930
1D012	Smoke Detector	Right Nurses Station	Photoelectric	29885959
1D013	Smoke Detector	Right Med Room	Photoelectric	29885960
1D014	Smoke Detector	Discovery Room	Photoelectric	29885884
1D015	Smoke Detector	Reception Desk	Photoelectric	29885881
1D016	Smoke Detector	Administrator Office	Photoelectric	29885878
1D017	Smoke Detector	Business Office	Photoelectric	29885879
1D018	Smoke Detector	Left Med Room	Photoelectric	29885968
1D019	Smoke Detector	Room 105	Photoelectric	29885898
1D020	Smoke Detector	Hall By Room 105	Photoelectric	29885976
1D021	Smoke Detector	Room 107	Photoelectric	29885899
1D022	Smoke Detector	Room 109	Photoelectric	29885900
1D023	Smoke Detector	Room 111	Photoelectric	29885902
1D024	Smoke Detector	Room 113	Photoelectric	29885904
1D025	Smoke Detector	Room 115	Photoelectric	29885988
1D026	Smoke Detector	Room 117	Photoelectric	29885986
1D027	Smoke Detector	Room 119	Photoelectric	29885984
1D028	Smoke Detector	Room 121	Photoelectric	29885983
1D029	Smoke Detector	Hall By Room 121	Photoelectric	29885981
1D030	Smoke Detector	Room 118	Photoelectric	29885985
1D031	Smoke Detector	Room 116	Photoelectric	29885987
1D032	Smoke Detector	Room 114	Photoelectric	29885989
1D033	Smoke Detector	Hall By Room 116	Photoelectric	29885980
1D034	Smoke Detector	Hall By Room 112	Photoelectric	29885979
1D035	Smoke Detector	Room 112	Photoelectric	29885905
1D036	Smoke Detector	Room 110	Photoelectric	29885903
1D037	Smoke Detector	Hall By Room 111	Photoelectric	29885978
1D038	Smoke Detector	Hall By Room 108	Photoelectric	29885977
1D040	Smoke Detector	Room 108	Photoelectric	29885901
1D041	Smoke Detector	Left Living Room Near Exit	Photoelectric	29885975
1D042	Smoke Detector	Hall At Special Care Coordinator	Photoelectric	29885887

1D043	Smoke Detector	Room 106	Photoelectric	29885897
1D044	Smoke Detector	Room 104	Photoelectric	29885896
1D045	Smoke Detector	Hall At Room 104	Photoelectric	29885889
1D046	Smoke Detector	Room 102	Photoelectric	29885895
1D047	Smoke Detector	Hall At Room 102	Photoelectric	29885891
1D048	Smoke Detector	Room 100	Photoelectric	29885894
1D049	Smoke Detector	Laundry Room	Photoelectric	29885893
1D050	Smoke Detector	Hall At Laundry Room	Photoelectric	29885892
1D051	Smoke Detector	Special Care Coordinator	Photoelectric	29885888
1D052	Smoke Detector	Dining Room By Activities Director	Photoelectric	29885965
1D053	Smoke Detector	Activities Director Office	Photoelectric	29885886
1D054	Smoke Detector	Dining Room By Kitchen	Photoelectric	29885964
1D055	Heat Detector	Kitchen	Fixed Temperature	29885874
1D058	Heat Detector	Kitchen	Fixed Temperature	29885875
1D059	Smoke Detector	Dining Room By Storage	Photoelectric	29885963
1D060	Smoke Detector	Hall By Room 126	Photoelectric	29885927
1D061	Smoke Detector	Room 126	Photoelectric	29885943
1D062	Smoke Detector	Room 124	Photoelectric	29885942
1D063	Smoke Detector	Hall By Room 124	Photoelectric	29885926
1D064	Smoke Detector	Personal Care Beauty Salon	Photoelectric	29885939
1D065	Smoke Detector	Hall At Employee Lounge	Photoelectric	29885925
1D066	Heat Detector	Outside Riser Room / Electrical Above FACP	Fixed Temperature	29885919
1D067	Smoke Detector	Room 122	Photoelectric	29885941
1D068	Smoke Detector	Room 120	Photoelectric	29885940
1D069	Smoke Detector	Exit By Room 120	Photoelectric	29885921
1D070	Smoke Detector	100 Employee Lounge	Photoelectric	29885924
1D071	Smoke Detector	Room 123	Photoelectric	29885944
1D072	Smoke Detector	Hall By Room 123	Photoelectric	29885931
1D073	Smoke Detector	Room 125	Photoelectric	29885945
1D074	Smoke Detector	Room 127	Photoelectric	29885946
1D075	Smoke Detector	Room 129	Photoelectric	29885948
1D076	Smoke Detector	Room 131	Photoelectric	29885951
1D077	Smoke Detector	Room 133	Photoelectric	29885952
1D078	Smoke Detector	Room 135	Photoelectric	29885954
1D079	Smoke Detector	Room 137	Photoelectric	29885957
1D080	Smoke Detector	Room 139	Photoelectric	29885958
1D081	Smoke Detector	Hall By Room 139	Photoelectric	29885936
1D082	Smoke Detector	Room 138	Photoelectric	29885956
1D083	Smoke Detector	Room 136	Photoelectric	29885955
1D084	Smoke Detector	Room 134	Photoelectric	29885953
1D085	Smoke Detector	Hall By Room 136	Photoelectric	29885935
1D086	Smoke Detector	Hall By Room 132	Photoelectric	29885934
1D087	Smoke Detector	Room 132	Photoelectric	29885950
1D088	Smoke Detector	Room 130	Photoelectric	29885949
1D090	Smoke Detector	Hall By Room 130	Photoelectric	29885933
1D091	Smoke Detector	Hall By Room 128	Photoelectric	29885932
1D092	Smoke Detector	Room 128	Photoelectric	29885947
1D093	Smoke Detector	Living Room By TV	Photoelectric	29885929
1D094	Smoke Detector	Living Room	Photoelectric	29885928
1D095	Smoke Detector	Clean Linen Right Side	Photoelectric	29885873
1M001	Pull Station	Left Nurse Station	Dual Action	29885970
1M002	Pull Station	Main Lobby	Dual Action	29885882

1M003	Pull Station	Exit By Room 121	Dual Action	29885982
1M004	Pull Station	Left Living Room Exit	Dual Action	29885973
1M005	Pull Station	Exit By Room 100	Dual Action	29885890
1M006	Pull Station	Kitchen	Dual Action	29885876
1M007	Pull Station	Exit By Room 120	Dual Action	29885920
1M008	Pull Station	Exit By Room 139	Dual Action	29885937