

Fax

ANT MARY'S FAMILY CARE HOME

P.O. BOX 516 LA GRANGE, N.C. 28551

252-566-5998

FAX 252-566-3598 OR 252-566-2878

To: Suzanna Fay **From:** Eula Conyers

Fax: 919-733-6592 **Pages:** 4

Date: 6-13-16

Urgent: For Review

Comments: Ant Mary's # 3

CONFIDENTIAL

This fax that you have received contains highly confidential and federally protected health information. If you are not the intended recipient listed above and have received this fax in error, please notify us and destroy your copy immediately. Use or release of any information contained in this document can and will be prosecuted under HIPAA (Health Insurance Portability and Accountability Act of 1996) guidelines

PRINTED: 06/06/2016
FORM APPROVED

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL054059	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED R 03/23/2016
NAME OF PROVIDER OR SUPPLIER ANT MARY'S FAMILY CARE HOME # 3		STREET ADDRESS, CITY, STATE, ZIP CODE 3713 HERRING ROAD LA GRANGE, NC 28551		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{C 000}	Initial Comments Report by Suzanna Fay DHSR Construction Section conducted a Biennial Follow-up Survey on March 23, 2016 from 10:33 AM to 11:09 AM at the above referenced facility. Not all of the previously cited deficiencies were corrected. Therefore, further action is required. The remaining deficiencies are as follows:	{C 000}		
{C 174}	Building Equipment Maintained Safe, Operating SECTION .0300 - THE BUILDING 10A NCAC 13G .0317 BUILDING SERVICE EQUIPMENT (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in a family care home shall be maintained in a safe and operating condition. (j) This Rule shall apply to new and existing family care homes. This Rule is not met as evidenced by: BEDROOM #1 4) During the survey, it was observed that several bedframe marks dotted the floor at the bed located on the outer wall. Contact a qualified technician to make the necessary repairs. Provide to our office copies of any documentation that verifies the repairs. 03/23/16: SF-Observations revealed a small tear in the vinyl floor where the bed posts have penetrated the flooring. Have a qualified technician repair the damaged floor and provide protection between the bed legs and flooring to prevent future damage. BEDROOM #2	{C 174}	0174 Section .0300. The Building 10A NCAC 13G. 0317 Building Service Equipment (a) the buildings and a fire safety, electrical mechanical and plumbing equipment in a family care home shall be maintained in a safe and operating condition Tears in the floor were glued back down. and coasters were placed under each bed post.	4/18/16

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

STATE FORM

8899

KYM322

If continuation sheet 1 of 3

PRINTED: 06/06/2016
FORM APPROVED

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL054059	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED R 03/23/2016
NAME OF PROVIDER OR SUPPLIER ANT MARY'S FAMILY CARE HOME # 3		STREET ADDRESS, CITY, STATE, ZIP CODE 3713 HERRING ROAD LA GRANGE, NC 28551	
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)
(C 174) Continued From page 1 3) During the survey, a depression was observed in the left wall. Contact a qualified technician to make the necessary repairs. Provide to our office copies of any documentation that verifies the repairs. 03/23/16: SF-Observations revealed that the wall was still damaged. Have a qualified technician patch the wall. Provide documentation of the repairs in the form of photos, receipts or work orders. BEDROOM #4 3) During the survey, it was observed that the door to the 1/2 bathroom has damage on the lower right corner. Contact a qualified technician to make the necessary repairs. Provide to our office copies of any documentation that verifies the repairs. 03/23/16: SF-Observations revealed that the finish is delaminating on the inside face of the door. Have a qualified technician repair the door. Provide documentation of the repairs in the form of photos, receipts or work orders. EXTERIOR 2) During the survey, it was observed that on the rear side of the home there is damage to the vinyl trim work which has exposed the wooden fascia board and soffit. Contact a qualified technician to make the necessary repairs. Provide to our office copies of any documentation that verifies the repairs. 03/23/16: SF-At the time of this survey, the damaged vinyl trim and soffit had not been repaired. Have a qualified technician repair the trim and soffit. Provide documentation of the repairs in the form of photos, receipts or work	(C 174)	B.) Putty was put in the wall depression and area Repainted Extra putty is Needed Bedroom #4 b.) Bathroom door to 1/2 bath was repaired and painted Exterior (2) Damaged vinyl ON FRIM was repaired	5/26/16

PRINTED: 06/06/2016
FORM APPROVED

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL054059	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____		(X3) DATE SURVEY COMPLETED R 03/23/2016
NAME OF PROVIDER OR SUPPLIER ANT MARY'S FAMILY CARE HOME # 3		STREET ADDRESS, CITY, STATE, ZIP CODE 3713 HERRING ROAD LA GRANGE, NC 28551		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
(C 174)	Continued From page 2 orders.	(C 174)		