

PRINTED: 06/08/2017
FORM APPROVED

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL071013	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 04/12/2017
NAME OF PROVIDER OR SUPPLIER MARY REBECCA'S VILLAGE		STREET ADDRESS, CITY, STATE, ZIP CODE 13605 US HWY 17 HAMPSTEAD, NC 28443		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	Initial Comments Report by Paul Dixon DHSR Construction Section conducted a Biennial Survey on April 12, 2017 from 10:15 AM to 11:30 AM at the above referenced facility. DHSR records indicate the home was first licensed on March 18, 2013 as a Family Care Home for six (6) ambulatory Residents (able to evacuate and respond without any physical or verbal assistance during a fire or other emergency). Based on this information we are requiring the home to maintain compliance with the following: the 2005 Rules 10A NCAC 13G for Family Care Homes, the 2012 North Carolina State Building Code - Section 425.2 - Residential Care Homes. At the time of our visit, we cited deficiencies that require an acceptable plan of correction. They are as follows:	C 000		
C 174	Building Equipment Maintained Safe, Operating SECTION .0300 - THE BUILDING 10A NCAC 13G .0317 BUILDING SERVICE EQUIPMENT (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in a family care home shall be maintained in a safe and operating condition. (j) This Rule shall apply to new and existing family care homes. This Rule is not met as evidenced by: Observations during the survey showed that the Kitchen range hood grease filter is dirty. Clean or replace the grease filter. Provide copies of all photographs and any other supporting documentation concerning this repair.	C 174	The Kitchen Range hood grease filter will be thoroughly cleaned monthly and grease surrounding the hood will be cleaned after each time the stove top is used.	4/24/17 6/9/17

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE





