

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL060109	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 05/25/2017
NAME OF PROVIDER OR SUPPLIER THE LITTLE FLOWER ASSISTED LIVING		STREET ADDRESS, CITY, STATE, ZIP CODE 8700 LAYWERS ROAD CHARLOTTE, NC 28227		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	Initial Comments Construction Section Biennial Survey report by Frank Strickland on 05/25/2017: This facility was first licensed on 08/16/1996. Therefore, we are requiring that this facility meet the 1994 "Regulations for Homes for the Aged and Disabled ; Minimum standards and Regulations and the applicable portions of the 2005 Regulations for Adult Care Homes of Seven or More Beds and the 1996 edition of the North Carolina State Building Code Volume I - General Construction - Section 409 Institutional Occupancy (Group I). Licensed for FORTY-NINE BEDS. Deficiencies have been cited and a Plan of Correction is required.	C 000		
C 189	Building Equipment Maintained Safe, Operating SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1-Based on observation, this facility has not maintained the building and all fire safety equipment in a safe condition. This could allow the spread of fire and/or smoke beyond the room of origin.	C 189		

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL060109	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 05/25/2017
NAME OF PROVIDER OR SUPPLIER THE LITTLE FLOWER ASSISTED LIVING		STREET ADDRESS, CITY, STATE, ZIP CODE 8700 LAYWERS ROAD CHARLOTTE, NC 28227		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 1 Findings on 05/25/2017: The Med Room entry door is out of adjustment and has air gaps around the door stops greater than 1/8 of an inch.	C 189		