

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL034019	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED R 04/17/2019
---	---	--	--

NAME OF PROVIDER OR SUPPLIER

STREET ADDRESS, CITY, STATE, ZIP CODE

C R T - GOLDEN LAMB REST HOME

**1515 GOLDEN LAMB COURT
WINSTON SALEM, NC 27105**

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{C 000}	Initial Comments Report of Biennial Follow Up Construction Survey by Ed Miller on 4-17-2019. Some deficiencies were not corrected. Further action is required.	{C 000}		
{C 189}	Building Equipment Maintained Safe, Operating SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 6. Based on observations, the Building fire safety was not maintained in a safe and operating condition. This could expose all to fire/smoke if not contained in Room or compartment of origin. Findings on 4-17-2019: c. Attic East Firewall - there are several PVC pipes not firestopped with fire collars as they penetrate the firewall. d. Attic East Firewall - there are several PVC pipes with large gaps around them not firestopped as they penetrate the firewall. f. Attic West Firewall - there are three open-ended sleeves with insulated pipes not firestopped as they penetrate the firewall. g. Attic West Firewall - there are three PVC sleeves with insulated pipes not firestopped with fire collars as they penetrate the firewall.	{C 189}	Pipes and open areas were sealed with fire stop.	5/14/19

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

STATE FORM

6899

XWNQ24

Admin Assistant

5/14/19

If continuation sheet 1 of 1