

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL051056	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 05/29/2019
NAME OF PROVIDER OR SUPPLIER THE VILLAS BENSON I		STREET ADDRESS, CITY, STATE, ZIP CODE 606 EAST MORRIS AVENUE BENSON, NC 27504		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	Initial Comments Report by Paul Dixon DHSR Construction Section conducted a Biennial Survey on May 29, 2019 from 8:30 AM to 9:45 AM at the above referenced facility. DHSR records indicate the home was first licensed on July 5, 2016 as a Family Care Home for six (6) ambulatory Residents (Who are able to respond and evacuate without any physical or verbal assistance during a fire or other emergency). Based on this information we are requiring the home to maintain compliance with the following: the 2005 Rules 10A NCAC 13G for Family Care Homes, and the applicable portions of the 2012 North Carolina State Building Code - Section 425.2 - Residential Care Homes. NOTES: 1.) At the time of our visit, we cited deficiencies that require an acceptable plan of correction. All deficiencies listed were discussed with on-site staff during the exit interview. 2.) Take actions to correct all listed deficiencies, once completed provide verification in the form of photos, receipts, invoices, etc. for all work performed.	C 000		
C 117	Have Current San. And Fire Safety Approvals SECTION .0300 - THE BUILDING 10A NCAC 13G .0302 DESIGN AND CONSTRUCTION (n) The home shall have current sanitation and fire and building safety inspection reports which shall be maintained in the home and available for review.	C 117		

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL051056	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 05/29/2019
NAME OF PROVIDER OR SUPPLIER THE VILLAS BENSON I		STREET ADDRESS, CITY, STATE, ZIP CODE 606 EAST MORRIS AVENUE BENSON, NC 27504		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 117	Continued From page 1 This Rule is not met as evidenced by: 1. At the time of the survey it was observed that the latest fire and sanitation inspections were not available for review. This is not compliant with the rule.	C 117		
C 148	Outside Entrances/Exits-Free of Obstructions SECTION .0300 - THE BUILDING 10A NCAC 13G .0312 OUTSIDE ENTRANCE AND EXITS (e) All entrances/exits shall be free of all obstructions or impediments to allow for full instant use in case of fire or other emergency. This Rule is not met as evidenced by: 1. At the time of the survey it was observed that in Bedroom #2, there was a dresser in front of the windows. This is not compliant with the rule. NOTE: This room was not occupied at the time of the survey. Insure that the dresser will be relocated prior to admitting a resident to the room.	C 148		
C 153	Houskeeping And Furnishings-Clean, Repaired SECTION .0300 - THE BUILDING 10A NCAC 13G .0315 HOUSEKEEPING AND FURNISHINGS (a) Each family care home shall: (1) have walls, ceilings, and floors or floor coverings kept clean and in good repair; (2) have no chronic unpleasant odors; (3) have furniture clean and in good repair; (e) This Rule shall apply to new and existing homes. This Rule is not met as evidenced by: 1. At the time of the survey it was observed that	C 153		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL051056	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 05/29/2019
NAME OF PROVIDER OR SUPPLIER THE VILLAS BENSON I		STREET ADDRESS, CITY, STATE, ZIP CODE 606 EAST MORRIS AVENUE BENSON, NC 27504		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 153	Continued From page 2 in the hall bathroom with the shower, areas of paint were peeling from the ceiling in the shower stall.. This is not compliant with the rule. 2. At the time of the survey it was observed that in the hall bathroom with the tub, several tiles were missing from the wall at the end of the tub. This is not compliant with the rule.	C 153		
C 174	Building Equipment Maintained Safe, Operating SECTION .0300 - THE BUILDING 10A NCAC 13G .0317 BUILDING SERVICE EQUIPMENT (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in a family care home shall be maintained in a safe and operating condition. (j) This Rule shall apply to new and existing family care homes. This Rule is not met as evidenced by: 1. At the time of the survey it was observed that the kitchen range hood filter was very greasy. This is not compliant with the rule.	C 174		