

North Dakota Department of Health

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 8019	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 - MAIN BUILDING 01 B. WING _____	(X3) DATE SURVEY COMPLETED 05/25/2021
NAME OF PROVIDER OR SUPPLIER SENIOR SUITES AT SAKAKAWEA		STREET ADDRESS, CITY, STATE, ZIP CODE 813 7TH ST NE HAZEN, ND 58545		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
K 000	INITIAL COMMENTS This survey used the 2012 edition of NFPA 101, Life Safety Code, Chapter 33 Existing Residential Board and Care Occupancies (Large), in compliance with NDAC 33-03-24.2. The facility was located in a one-story building of Type V (111) construction. It was equipped with a manual fire alarm system and an automatic smoke detection system in habitable areas. Based on resident evaluation, a slow level of evacuation difficulty was determined. E-Score was 1.95. Note: Observation and records review determined the facility to be in compliance with the minimum requirements of the 2012 Life Safety Code.	K 000		

Health Resources Section

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE