

Division of Health Improvement

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 4079	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 03/25/2019
NAME OF PROVIDER OR SUPPLIER SENIORCARE LLC - SOLANO HOUSE		STREET ADDRESS, CITY, STATE, ZIP CODE 1419 SOLANO DR NE ALBUQUERQUE, NM 87110		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
A 000	Initial Comments On March 25, 2019 an initial Life Safety Code survey was conducted at the above referenced facility per the provider's request. The facility is found to be in substantial compliance with the Life Safety Code of the New Mexico State Regulations for Assisted Living Facilities for Adults, 7 NMAC 8.2. Temporary Licensure is recommended.	A 000		

Division of Health Improvement

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE