

Division of Health Improvement

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 2216	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 10/31/2012
NAME OF PROVIDER OR SUPPLIER LIFE SPIRE ASSISTED LIVING OF RIO RANCHO		STREET ADDRESS, CITY, STATE, ZIP CODE 1001 24TH ST RIO RANCHO, NM 87124		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
A 000	Initial Comments On October 31, 2012, an initial Life Safety Code survey was conducted at the facility per the provider's request. This facility was found to be in substantial compliance with the Life Safety Code portion of the New Mexico State Requirements for Assisted Living Facilities for Adults 7 NMAC 8.2 I recommended temporary licensure for a capacity of 30 residents.	A 000		

Division of Health Improvement

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE