



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Woodland Village	Provider Number	2512
Address	2100 SW WOODLAND CIR ,	Approval Status	Approved
City, State, Zip	Chehalis, WA 98532	Facility Type	Residential Care

On 08/25/2023 the Office of the State Fire Marshal conducted an inspection at your facility.

All violations noted during previous related inspection(s) have been corrected.

Owner or Owner's Representative

Kiersten Milton
Signature

Kiersten Milton Executive Director
Print Name and Title

Deputy State Fire Marshal Nicholas Wolden
1823 BAKER WAY
Kelso WA 98626
(360) 852-0966

[Signature]
Signature

This document was prepared by Residential Care Services for the Locator website.

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.



Washington State Patrol
Fire Protection Bureau

Phone: (360) 596-3900

Business Name	Woodland Village	Provider Number	2512
Address	2100 SW WOODLAND CIR ,	Approval Status	Disapproved
City, State, Zip	Chehalis, WA 98532	Facility Type	Residential Care

On 07/06/2023 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

1 Owner's Responsibility

The owner shall maintain an inventory of all required fire-resistance-rated construction, construction installed to resist the passage of smoke and the construction included in Sections 703 through 707 and Sections 602.4.1 and 602.4.2 of the International Building Code. Such construction shall be visually inspected by the owner annually and properly repaired, restored or replaced where damaged, altered, breached or penetrated. Records of inspections and repairs shall be maintained. Where concealed, such elements shall not be required to be visually inspected by the owner unless the concealed space is accessible by the removal or movement of a panel, access door, ceiling tile or similar movable entry to the space.

(IFC 701.6 2018 WAC 51-54A)

Facility failed to present fire rated inventory and annual inspection

2 Inspection and Maintenance

Opening protectives in fire-resistance-rated assemblies shall be inspected and maintained in accordance with NFPA 80. Opening protectives in smoke barriers shall be inspected and maintained in accordance with NFPA 80 and NFPA 105. Openings in smoke partitions shall be inspected and maintained in accordance with NFPA 105. Fire doors and smoke and draft control doors shall not be blocked, obstructed, or otherwise made inoperable. Fusible links shall be replaced promptly whenever fused or damaged. Opening protectives and smoke and draft control doors shall not be modified.

(IFC 705.2 2018)

Facility failed to provide annal fire door inspection report.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Woodland Village	Provider Number	2512
Address	2100 SW WOODLAND CIR ,	Approval Status	Disapproved
City, State, Zip	Chehalis, WA 98532	Facility Type	Residential Care

On 07/06/2023 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

3 Duct and Air Transfer Openings - Maintaining Protection

Dampers protecting ducts and air transfer openings shall be inspected and maintained in accordance with NFPA 80 and NFPA 105. Other products or materials used to protect the openings for ducts and air transfer openings shall be securely attached to or bonded to the construction containing the duct or air transfer opening, without visible openings through or into the cavity of the construction. Any damaged products or materials protecting duct and air transfer openings shall be repaired, restored or replaced.

(IFC 706.1 2018)

Facility failed to provide fire damper testing. Dampers shall be tested 1 year after installation. Fire damper inspector shall be certified to RCW 19.27.720

4 Inspection, Testing and Maintenance

Fire detection and alarm systems, emergency alarm systems, gas detection systems, fire-extinguishing systems, mechanical smoke exhaust systems and smoke and heat vents shall be maintained in an operative condition at all times, and shall be replaced or repaired where defective. Nonrequired fire protection systems and equipment shall be inspected, tested and maintained or removed.

(IFC 901.6 2018)

Facility failed to provide annual forward flow testing documentation

5 Extinguishing System Service

Automatic fire-extinguishing systems shall be serviced not less frequently than every six months and after activation of the system. Inspection shall be by qualified individuals, and a certificate of inspection shall be forwarded to the fire code official upon completion.

(IFC 904.12.5.2 2018)

Kitchen hood suppression system shall have a heat survey conducted and documented. Fusible links shall be installed in accordance with results of heat survey and manufacture requirements.

6 Power Test

Battery-powered emergency lighting equipment shall be tested annually by operating the equipment on battery power for not less than 90 minutes.

(IFC 1031.10.2 2018)

Facility failed to provide annual emergency lighting of exit signs and emergency lighting



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Woodland Village	Provider Number	2512
Address	2100 SW WOODLAND CIR ,	Approval Status	Disapproved
City, State, Zip	Chehalis, WA 98532	Facility Type	Residential Care

On 07/06/2023 the Office of the State Fire Marshal conducted an inspection at your facility.


Code Requirement

Statement of Violation

Next inspection scheduled on or after: 08/05/2023

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Authorized Representative


Signature

Kiersten Milton Executive Director
Print Name and Title

Deputy State Fire Marshal Nicholas Wolden
1823 BAKER WAY
Kelso WA 98626
(360) 852-0966


Signature