



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

2

Business Name Sycamore Glen at Quail Hollow

Address 506 N EHORN LN,

City, State, Zip Chewelah, WA

Provider Number 2556

Approval Status Approved

Facility Type Residential Care

On 02/27/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

1 Admin - (ITM) Inspection, Testing, & Maintenance

Any citation that requires inspection, testing, or maintenance (ITM) is required to have the testing completed, paper results delivered, and any deficiencies found during the ITM corrected before the citation is cleared."

Extension requested for fire damper testing by JuLee Childress until 2/28/26.

2 Repair of penetrations

Repair of penetrations. Where damaged, materials used to protect membrane- and through-penetrations shall be replaced or restored with materials or systems that meet or exceed the code requirements applicable at the time when the assembly was constructed, remodeled or altered.

Corrected.

3 Inspection, Testing and Maintenance

The maintenance and testing schedules and procedures for fire alarm and fire detection systems shall be in accordance with Sections 907.8.1 through 907.8.5 and NFPA 72. Records of inspection, testing and maintenance shall be maintained.

(IFC 907.8 2021)

2/25/26 report received.

4 NFPA 80 Fire /Smoke Dampers Inspection and Testing

19.4 Periodic Inspection and Testing.

19.4.1 Each damper shall be tested and inspected 1 year after installation.

19.4.1.1 The test and inspection frequency shall then be every 4 years, except in hospitals, where the frequency shall be every 6 years.

2/11/26 report received.

This document was prepared by Residential Care Services for the Locator website.

Initials of Authorized Facility Representative: 



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

9

Business Name Sycamore Glen at Quail Hollow

Provider Number 2556

Address 506 N EHORN LN ,

Approval Status Approved

City, State, Zip Chewelah, WA

Facility Type Residential Care

On 02/27/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

Next inspection scheduled on or after: 11/09/2026

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Authorized Representative

Signature

Print Name and Title

Deputy State Fire Marshal Barbara McMullen
6403 W ROWAND DR
Spokane WA 99219
(509) 954-2746

Signature



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name Sycamore Glen at Quail Hollow
Address 506 N EHORN LN ,
City, State, Zip Chewelah, WA

Provider Number 2556
Approval Status Disapproved
Facility Type Residential Care

On 10/31/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

1 Admin - (ITM) Inspection, Testing, & Maintenance

Any citation that requires inspection, testing, or maintenance (ITM) is required to have the testing completed, paper results delivered, and any deficiencies found during the ITM corrected before the citation is cleared."

For your information.

2 Relocatable power taps and current taps

Relocatable power taps and current taps. The construction and use of current taps and relocatable power taps shall be in accordance with NFPA 70 and this code.
(IFC 603.5, 2021)

The following violation was observed:
In room 13 a multiplug adapter was plugged into a powerstrip.
Removed at inspection.

3 Repair of penetrations

Repair of penetrations. Where damaged, materials used to protect membrane- and through-penetrations shall be replaced or restored with materials or systems that meet or exceed the code requirements applicable at the time when the assembly was constructed, remodeled or altered.

The following violation was observed:
There are penetrations in the following locations:
1. Administrator office in the ceiling.
2. Hallway by restroom in the wall.

4 Inspection, Testing and Maintenance

The maintenance and testing schedules and procedures for fire alarm and fire detection systems shall be in accordance with Sections 907.8.1 through 907.8.5 and NFPA 72. Records of inspection, testing and maintenance shall be maintained.
(IFC 907.8 2021)

The following violation was observed:
Facility is unable to provide documentation for the annual fire alarm system testing and maintenance.

5 NFPA 80 Fire /Smoke Dampers Inspection and Testing

19.4 Periodic Inspection and Testing.
19.4.1 Each damper shall be tested and inspected 1 year after installation.
19.4.1.1 The test and inspection frequency shall then be every 4 years, except in hospitals, where the frequency shall be every 6 years.

The following violation was observed:
Last report on Fire/Smoke testing and service is from 2021, facility is reminded that Fire/Smoke 4-year Inspection/testing is due before the end of 2025.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name Sycamore Glen at Quail Hollow
Address 506 N EHORN LN ,
City, State, Zip Chewelah, WA

Provider Number 2556
Approval Status Disapproved
Facility Type Residential Care

On 10/31/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

Next inspection scheduled on or after: 11/30/2025


Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Authorized Representative


Signature

Julie Childress; Administrator
Print Name and Title

Deputy State Fire Marshal Barbara McMullen
6403 W ROWAND DR
Spokane WA 99219
(509) 954-2746


Signature

This document was prepared by Residential Care Services for the Locator website.