

Wisconsin Department of Health Services

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 0017076	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING: _____	(X3) DATE SURVEY COMPLETED 06/03/2024
NAME OF PROVIDER OR SUPPLIER POUND AFH 2		STREET ADDRESS, CITY, STATE, ZIP CODE 1005 COUNTY DR POUND, WI 54161		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
M 000	INITIAL COMMENTS An abbreviated survey was conducted at Pound AFH 2 on 05/29/2024 with information gathered through 06/03/2024. As a result of this survey 1 deficient practice was identified. Census: 4	M 000		
M 570	88.10(3)(I) Safe Physical Environment Individuals, except for correctional residents, have basic rights which they do not lose when they enter an adult family home. A resident shall have a safe environment in which to live. The adult family home shall safeguard residents who cannot fully guard themselves from environmental hazards to which they are likely to be exposed, including conditions which would be hazardous to anyone and conditions which would be or are hazardous to a particular resident because of the resident's condition or disability. This Rule is not met as evidenced by: Based on observation and staff interview the provider did not ensure that 4 of 4 residents were kept safe from hazardous water temperatures in this facility. Hot water temperatures in resident bathrooms were noted to be 128.4 degrees F (Fahrenheit) and 124.4 degrees F. Findings include: This facility is licensed as a non-ambulatory home and serves residents with developmental disabilities, irreversible dementia/Alzheimer's, physically disabled, or traumatic brain injury.	M 570		

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Wisconsin Department of Health Services

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 0017076	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING: _____	(X3) DATE SURVEY COMPLETED 06/03/2024
NAME OF PROVIDER OR SUPPLIER POUND AFH 2		STREET ADDRESS, CITY, STATE, ZIP CODE 1005 COUNTY DR POUND, WI 54161		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
M 570	Continued From page 1 On 05/29/2024, Surveyor tested water temperatures in resident bathrooms during tour. At 1:20 PM the water temperature in the resident bathroom with the shower next to the laundry room tested at 128.3 degrees F and was verified by LIC (Licensee) - A. The hot water temperature in a second resident bathroom tested at 124.4 degrees F. Exposure to hot water is a potential environmental danger for residents. Elderly residents and residents with mental and physical disabilities may have neurological conditions that prevent instant recoil from hot water. Because these individuals do not instantly react to dangerous temperature levels, they are at particular risk for injury. Hot water can cause scalding, e.g., second and third degree burns in which the skin blisters and swells. In such instances, skin does not return to normal and forms scar tissue upon healing. These burns may lead to permanent disability. (DQA Publication-01942, Hot Water Temperatures in Adult Family Homes, August 2017.) There were no concerns from residents during interviews with the Surveyor of water temperatures being too hot.	M 570		