

2/12/2015

State Form: Revisit Report

(Y1) Provider / Supplier / CLIA / Identification Number ALF010	(Y2) Multiple Construction A. Building B. Wing	(Y3) Date of Revisit 02/12/2015
---	--	------------------------------------

Name of Facility
BEE HIVE HOMES OF EVANSTON

Street Address, City, State, Zip Code
1949 WEST UINTA STREET
EVANSTON, WY 82930

This report is completed by a State surveyor to show those deficiencies previously reported that have been corrected and the date such corrective action was accomplished. Each deficiency should be fully identified using either the regulation or LSC provision number and the identification prefix code previously shown on the State Survey Report (prefix codes shown to the left of each requirement on the survey report form).

(Y4) Item	(Y5) Date	(Y4) Item	(Y5) Date	(Y4) Item	(Y5) Date
ID Prefix <u>S8004</u> Reg. # <u>NFPA</u> LSC _____	Correction Completed 01/14/2015	ID Prefix <u>S8022</u> Reg. # <u>NFPA</u> LSC _____	Correction Completed 01/12/2015	ID Prefix <u>S8028</u> Reg. # <u>NFPA</u> LSC _____	Correction Completed 01/12/2015
ID Prefix _____ Reg. # _____ LSC _____	Correction Completed	ID Prefix _____ Reg. # _____ LSC _____	Correction Completed	ID Prefix _____ Reg. # _____ LSC _____	Correction Completed
ID Prefix _____ Reg. # _____ LSC _____	Correction Completed	ID Prefix _____ Reg. # _____ LSC _____	Correction Completed	ID Prefix _____ Reg. # _____ LSC _____	Correction Completed
ID Prefix _____ Reg. # _____ LSC _____	Correction Completed	ID Prefix _____ Reg. # _____ LSC _____	Correction Completed	ID Prefix _____ Reg. # _____ LSC _____	Correction Completed
ID Prefix _____ Reg. # _____ LSC _____	Correction Completed	ID Prefix _____ Reg. # _____ LSC _____	Correction Completed	ID Prefix _____ Reg. # _____ LSC _____	Correction Completed
ID Prefix _____ Reg. # _____ LSC _____	Correction Completed	ID Prefix _____ Reg. # _____ LSC _____	Correction Completed	ID Prefix _____ Reg. # _____ LSC _____	Correction Completed

Reviewed By State Agency	Reviewed By <u>TS 2/13/15</u>	Date:	Signature of Surveyor: <u>[Signature] 34354</u>	Date: <u>2/12/15</u>
Reviewed By CMS RO	Reviewed By	Date:	Signature of Surveyor:	

Followup to Survey Completed on: 01/12/2015	Check for any Uncorrected Deficiencies. Was a Summary of Uncorrected Deficiencies (CMS-2567) Sent to the Facility? YES NO
--	--