

State Form: Revisit Report

(Y1) Provider / Supplier / CLIA / Identification Number 535025	(Y2) Multiple Construction A. Building 01 - MAIN BUILDING 01 B. Wing	(Y3) Date of Revisit 10/28/2015
Name of Facility CHEYENNE HEALTH CARE CENTER		Street Address, City, State, Zip Code 2700 E 12TH STREET CHEYENNE, WY 82001

This report is completed by a State surveyor to show those deficiencies previously reported that have been corrected and the date such corrective action was accomplished. Each deficiency should be fully identified using either the regulation or LSC provision number and the identification prefix code previously shown on the State Survey Report (prefix codes shown to the left of each requirement on the survey report form).

(Y4) Item	(Y5) Date	(Y4) Item	(Y5) Date	(Y4) Item	(Y5) Date
Correction Completed		Correction Completed		Correction Completed	
ID Prefix S7015	09/08/2015	ID Prefix S7035	10/19/2015	ID Prefix	
Reg. # NFPA		Reg. # IMC		Reg. #	
LSC		LSC		LSC	
Correction Completed		Correction Completed		Correction Completed	
ID Prefix		ID Prefix		ID Prefix	
Reg. #		Reg. #		Reg. #	
LSC		LSC		LSC	
Correction Completed		Correction Completed		Correction Completed	
ID Prefix		ID Prefix		ID Prefix	
Reg. #		Reg. #		Reg. #	
LSC		LSC		LSC	
Correction Completed		Correction Completed		Correction Completed	
ID Prefix		ID Prefix		ID Prefix	
Reg. #		Reg. #		Reg. #	
LSC		LSC		LSC	
Correction Completed		Correction Completed		Correction Completed	
ID Prefix		ID Prefix		ID Prefix	
Reg. #		Reg. #		Reg. #	
LSC		LSC		LSC	
Correction Completed		Correction Completed		Correction Completed	
ID Prefix		ID Prefix		ID Prefix	
Reg. #		Reg. #		Reg. #	
LSC		LSC		LSC	
Reviewed By State Agency	Reviewed By Date: 10/21/15	Signature of Surveyor Date: 10/29/15	Signature of Surveyor 34354		
Reviewed By CMS RO	Reviewed By	Signature of Surveyor			
Followup to Survey Completed on:		Check for any Uncorrected Deficiencies. Was a Summary of Uncorrected Deficiencies (CMS-2567) Sent to the Facility? YES NO			