

STATE FORM: REVISIT REPORT

PROVIDER / SUPPLIER / CLIA / IDENTIFICATION NUMBER ALF013	MULTIPLE CONSTRUCTION A. Building B. Wing	DATE OF REVISIT 9/22/2016
NAME OF FACILITY SHOWBOAT RETIREMENT CENTER	STREET ADDRESS, CITY, STATE, ZIP CODE 150 WYOMING STREET LANDER, WY 82520	

This report is completed by a State surveyor to show those deficiencies previously reported that have been corrected and the date such corrective action was accomplished. Each deficiency should be fully identified using either the regulation or LSC provision number and the identification prefix code previously shown on the State Survey Report (prefix codes shown to the left of each requirement on the survey report form).

ITEM Y4	DATE Y5	ITEM Y4	DATE Y5	ITEM Y4	DATE Y5
ID Prefix S8008	Correction	ID Prefix S8022	Correction	ID Prefix S8027	Correction
Reg. # NFPA	Completed	Reg. # NFPA	Completed	Reg. # NFPA	Completed
LSC	06/01/2016	LSC	06/01/2016	LSC	06/01/2016
ID Prefix S8028	Correction	ID Prefix S8999	Correction	ID Prefix	Correction
Reg. # NFPA	Completed	Reg. # State Miscellaneous	Completed	Reg. #	Completed
LSC	06/01/2016	LSC	06/01/2016	LSC	
ID Prefix	Correction	ID Prefix	Correction	ID Prefix	Correction
Reg. #	Completed	Reg. #	Completed	Reg. #	Completed
LSC		LSC		LSC	
ID Prefix	Correction	ID Prefix	Correction	ID Prefix	Correction
Reg. #	Completed	Reg. #	Completed	Reg. #	Completed
LSC		LSC		LSC	
ID Prefix	Correction	ID Prefix	Correction	ID Prefix	Correction
Reg. #	Completed	Reg. #	Completed	Reg. #	Completed
LSC		LSC		LSC	

REVIEWED BY STATE AGENCY ☐	REVIEWED BY (INITIALS) <i>DS</i>	DATE 11/15/16	SIGNATURE OF SURVEYOR <i>[Signature]</i>	DATE 11-15-16
REVIEWED BY CMS RO ☐	REVIEWED BY (INITIALS)	DATE	TITLE	DATE

FOLLOWUP TO SURVEY COMPLETED ON 4/6/2016

☐ CHECK FOR ANY UNCORRECTED DEFICIENCIES. WAS A SUMMARY OF UNCORRECTED DEFICIENCIES (CMS-2567) SENT TO THE FACILITY? ☐ YES ☐ NO