

PRINTED: 11/18/2016
FORM APPROVED

Healthcare Licensing and Surveys

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: WY0037	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING: _____	(X3) DATE SURVEY COMPLETED 11/03/2016
NAME OF PROVIDER OR SUPPLIER WIND RIVER REHABILITATION AND WELLNESS		STREET ADDRESS, CITY, STATE, ZIP CODE 1002 FOREST DRIVE RIVERTON, WY 82501		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
S2924	Ch 11 Sec 6 (a)(iv) Physical Environment (a) The building(s) of the Nursing Care Facility shall be constructed, arranged and maintained to ensure the health and welfare of all residents. (iv) Shower/bath and resident lavatories shall be set to provide water of a temperature not to exceed 110 degrees Fahrenheit. This State Rule and Regulation is not met as evidenced by: Based on observation and staff interview, the facility failed to ensure hot water temperatures in resident rooms did not exceed 110 degrees Fahrenheit (F) in 3 of 4 resident hallways (Secure Unit, South hall, North hall). The findings were: 1. Observation of the South hall on 10/31/16 showed the following: a. At 3:05 PM the temperature of the hot water in room 39 was 115.7 degrees F. b. At 3:10 PM the temperature of the hot water in room 43 was 116.8 degrees F. 2. Observation of the secure unit on 11/1/16 showed the following: a. At 8:10 AM the temperature of the hot water in room 23 was 114.8 degrees F. b. At 8:20 AM the temperature of the hot water in room 21 was 116.6 degrees F. c. At 8:30 AM the temperature of the hot water in room 19 was 116.5 degrees F. d. At 8:35 AM the temperature of the hot water in room 22 was 114.9 degrees F. 3. Observation of the North hall on 11/2/16 showed the following: a. At 11:25 AM the temperature of the hot water in room 25 was 118.1 degrees F. b. At 11:30 AM the temperature of the hot	S2924	This Plan of Correction is the facility's credible allegation of compliance. Preparation and/or execution of this Plan of Correction does not constitute admission or agreement by the provider of the truth of the facts alleged or conclusions set forth in the statement of deficiencies. The Plan of Correction is prepared and/or executed solely because it is required by the provisions of federal and state laws. S2924 The water temperature in the observed resident rooms on the south hall, the secure unit and north hall will set to be not above 110 degrees. Identification of Others: Audits of each resident room will be completed to identify any water temperature not within the range of regulations by Maintenance Director and/or designee. Systemic Changes: Director of Building Plant and Safety and/or designee will provide education to staff relating to the water	12.2.16

Wyoming Dept of Health, Aging Division, Healthcare Licensing and Surveys
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

STATE FORM

If continuation sheet 1 of 2

POC accepted. Call to Jeanne Ables, WDA on 10/20/16 re: 302-
407711
J. Ables

Healthcare Licensing and Surveys

PRINTED: 11/18/2016
FORM APPROVED

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: WY0037	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING: _____	(X3) DATE SURVEY COMPLETED 11/03/2016
---	---	--	---

NAME OF PROVIDER OR SUPPLIER
WIND RIVER REHABILITATION AND WELLNESS

STREET ADDRESS, CITY, STATE, ZIP CODE
1002 FOREST DRIVE
RIVERTON, WY 82501

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
S2924	Continued From page 1 water in room 28 was 114.6 degrees F. c. At 11:40 AM the temperature of the hot water in room 18 was 113.9 degrees F. d. At 12:09 PM the temperature of the hot water in room 2 was 116.5 degrees F. e. At 12:05 PM the temperature of the hot water in room 3 was 116.9 degrees F. f. At 12:08 PM the temperature of the hot water in room 4 was 115.3 degrees F. 4. Interview with the maintenance supervisor on 11/3/16 at 8:10 AM verified the temperature of the hot water exceeded 110 degrees F.	S2924	S2924 Cont'd: temperature in resident rooms. Water temperature audits will be added to the weekly maintenance rounds. Monitoring: Maintenance Director and/or designee will conduct audits of water temperature in resident rooms for temperatures being not being above 110 degrees. Results of the audits will be brought to the quality assurance meeting at least monthly until the correction is sustained.	